

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET

#04/#05 IOB BUILDING

SINGAPORE 049711

SLU1225J

ESTIMATE

VEHICLE NO : SMA6283B

MAKE/MODEL : BMW 428i

ACC DATE : 02.06.2022

PARTICULAR

NETT ITEM

AMOUNT

QTY	NETT ITEM	SS	SS
1	1 FRONT BUMPER <i>re/wash</i>	1,889.43	1,889.43
2	1 FRONT BUMPER BMW LOGO <i>11</i>	89.95	89.95
3	1 FRONT BUMPER SIDE GRILLE <i>11</i>	180.35	180.35
4	2 FRONT BUMPER SIDE RETAINERS -R/L <i>11</i>	89.95	179.90
5	1 FRONT BUMPER SPONGE <i>11</i>	181.62	181.62
6	1 FRONT BUMPER SPRAY NOZZLE COVER -LH <i>11</i>	81.65	81.65
			2,602.90
		LESS 5%	130.15
			2,472.76
SPECIAL NETT ITEM			
1	1 (SET) FRONT BUMPER CLIP <i>new</i>	50.00	50.00
			50.00
LABOUR CHARGES :			
1	TO CHECK FRONT ELECTRICAL WIRING		<i>11</i> 40.00
5	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		400.00
6	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS		400.00
			840.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 3,362.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: