

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22005488/AQY3E2**Date:** 20/01/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMQ5465R**Insured Vehicle No :** SJZ737C

Date of Loss: 07/06/2022

Nature of Claim: TP

Claim No: CDMPG22001083-002

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMQ5465R**

Make & Model: TOYOTA VIOS, 1.5 (A)

Engine No: 2NR5372343

Reg. Date: 25/11/2019 (Man. Year: 2019)

Chassis No: MR2B23F3X01181665

Colour: Silver

Odometer: 51089 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,520.52	1,399.35	1,121.17	44.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	970.00	1,240.00	56.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,730.52	2,369.35	2,361.17	49.91
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	4,730.52	1,900.00	2,830.52	59.84
+ GST 8.00/8.00% (S\$)	378.44	152.00	226.44	59.84
Nett Amount (S\$)	5,108.96	2,052.00	3,056.96	59.84

INSPECTION

Date of Assignment: 09/06/2022

Date Inspected: 09/06/2022 Inspected At:

Kang Car Repairers Pte Ltd (HQ)

No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jan 2023)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ5465R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	482.60 FL	*482.60 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	316.60 FL	*316.60 FL
3	1		*REAR BUMPER SIDE RETAINER RH	Necessary	113.90 FL	*113.90 FL
4	1		*REAR BUMPER RETAINER (SMALL) RH	Not Necessary	90.60 FL	*- FL
5	1		*REAR BUMPER REFLECTOR - RH	Cracked	123.70 FL	*123.70 FL
6	1		*TAIL LAMP - RH	Not Necessary	397.70 FL	*- FL
7	1		*REAR PANEL	Not Necessary	620.20 FL	*- FL
8	1		*REAR PANEL TRIM	Deformed	232.20 FL	*232.20 FL
9	1		*BOOT LID RUBBER	Not Necessary	166.40 FL	*- FL
10	1		*BOOT LID VIOS EMBLEM	Necessary	43.60 FL	*43.60 FL
11	1		*BOOT LID E EMBLEM	Necessary	33.20 FL	*33.20 FL
12	2		*L PLATE BRACKET	Necessary	80.00 FS	*50.00 FS
13	1		*SET REAR BUMPER STICKER	Necessary	280.00 FS	*240.00 FS
14	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
15	1		*L PLATE	Bent	80.00 FS	*60.00 FS
16	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*10.00 FS
17	1		*BOOT LID NUMBER 664 STICKER	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,175.70	1,735.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	655.18	336.45
Total Parts (\$\$)	2,520.52	1,399.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REPLACE STICKER	New	80.00	0.00
3	TO SPRAY UNDERSEAL	New	80.00	40.00
4	(REAR) TO SPRAY PAINTING	New	1,000.00	500.00
5	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING / WELDING WORKS	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,210.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >