

Vehicle Damage Assessment Report for [SMQ5465R]

Estimate Created: 18/01/2023 23:17 by Insurlogic 5 (Insurlogic_Pte_Ltd)

Owned: 18/01/2023 23:24 by Insurlogic 5 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO INSURANCE	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Vios
Engine Type			
License Plate Number	SMQ5465R	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$1900.00 with 4 days for repair

Insurlogic 5 (18/01/2023 23:23)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REAR BUMPER		1	482.60	-25.00 %	361.95
REAR BUMPER REINFORCEMENT		1	316.60	-25.00 %	237.45
REAR BUMPER SIDE RETAINER RH		1	114.90	-25.00 %	86.18
REAR BUMPER REFLECTOR RH		1	123.70	-25.00 %	92.78
END PANEL TRIM		1	232.20	-25.00 %	174.15
VIOS EMBLEM		1	43.60	-25.00 %	32.70
E EMBLEM		1	33.20	-25.00 %	24.90

Parts Subtotal 1,010.11

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
L PLATE BRACKET		1.0	50.00	0.00 %	50.00
REAR BUMPER STICKER		1.0	240.00	0.00 %	240.00
REAR BUMPER CLIPS		1.0	30.00	0.00 %	30.00
L PLATE		1.0	60.00	0.00 %	60.00
REAR END PANEL TRIM CLIPS		1.0	10.00	0.00 %	10.00

Materials Subtotal 390.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
CHECK WIRING	RnR	30.00	0.00 %	30.00
UNDERSEAL	RnR	40.00	0.00 %	40.00
REPLACE/REPAIR ACCIDENT AFFECTED AREAS	RnR	400.00	0.00 %	400.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	500.00	0.00 %	500.00

General Labor Subtotal 470.00

Paint Labor Subtotal	500.00
Labor Subtotal	970.00

Summary

Repair Cost	2,370.11
Discount(20 %)	(470.10)
	1,900.01
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	1,900.01