

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199

FAX: 68299247

ATTN: Motor Claim Department

Estimate No: EST2200180

Date: 08 Jun 2022

Veh Reg No: SMQ5465R

Make/Model: TOYOTA VIOS
1.5E(AUTO)

Chasis No: MR2B23F3X01181665

Reg. Date: 25/11/2019

Your Ref No: SJZ737C

Claim Type: Third Party

Accident Date: 07/06/2022

TP Veh Reg No: SJZ737C

xiao Chen

Estimate Repair Cost to Vehicle No :SMQ5465R

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC REAR BUMPER <i>Del-d</i>	482.60	✓
2	1 PC REAR BUMPER REINFORCEMENT <i>But</i>	316.60	✓
3	1 PC REAR BUMPER SIDE RETAINER RH <i>Heu</i>	113.90	✓
4	1 PC REAR BUMPER RETAINER (SMALL) RH <i>Heu</i>	90.60	✓
5	1 PC REAR BUMPER REFLECTOR - RH <i>Emb-d</i>	123.70	✓
6	1 PC TAIL LAMP - RH <i>Heu</i>	397.70	✓
7	1 PC REAR PANEL <i>Heu</i>	620.20	✓
8	1 PC REAR PANEL TRIM <i>Del-d</i>	232.20	✓
9	1 PC BOOT LID RUBBER <i>Heu</i>	166.40	✓
10	1 PC BOOT LID "VIOS" EMBLEM <i>Heu</i>	43.60	✓
11	1 PC BOOT LID "E" EMBLEM <i>Heu</i>	33.20	✓
		2,620.70	
Less 25%		655.18	1,965.54
Special Net			
12	2 PCS "L" PLATE BRACKET <i>Heu</i>	80.00 50	
13	1 SET REAR BUMPER STICKER <i>Heu</i>	280.00 240	
14	1 SET REAR BUMPER CLIPS <i>Heu</i>	40.00 30	
15	1 PC "L" PLATE <i>Bea</i>	80.00 60	
16	1 SET REAR PANEL TRIM CLIPS <i>Heu</i>	40.00 10	
17	1 PC BOOT LID NUMBER '664' STICKER <i>Heu</i>	35.00	✓
		555.00	555.00
Labour			
18	1 TO CHECK WIRING	50.00 30	
19	1 TO REPLACE STICKER	80.00	✓
20	1 TO SPRAY UNDERSEAL	80.00 40	
21	1 (REAR) TO SPRAY PAINTING	1,000.00 500	

1345.80
1009.35

390

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 07/06/2022
TP Veh Reg No: SJZ737C

Estimate No: EST2200180
Date: 08 Jun 2022

Veh Reg No: SMQ5465R
Make/Model: TOYOTA VIOS
1.5E(AUTO)
Chasis No: MR2B23F3X01181665
Reg. Date: 25/11/2019
Your Ref No: SJZ737C

Estimate Repair Cost to Vehicle No :SMQ5465R

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
22	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 970	400
		2,210.00	2,210.00
	Total		S\$ 4,730.54
	Add GST @ 7%		331.14
	Total Amount Payable		<u>S\$ 5,061.68</u>

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SIXTY ONE AND CENTS SIXTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
H/S 09/06/22.

04 Days.

Total: 2369.35

H/S: 1.9K.

042p 1.9K