

HS1A0209

Not Authorized
dhr

9/6/22

1/5 @ 16,000

12 days.

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

VEHICLE No : SMP 8125H

1PC	BONNET		R	\$1,125.00	X
1PC	FRONT BUMPER		D11	\$1,021.00	—
1PC	FRONT BUMPER SIDE RETAINER O/S		CRU	\$65.00	—
1PC	FRONT BUMPER BEAM		111	\$542.00	X
1SET	FRONT BUMPER CLIPS		111	\$50.00	—
1PC	FRONT BUMPER TOP GARNISH	320	TOCN	\$485.00	—
1PC	FRONT BUMPER TOP CHROME MOULDING	655.30	CRU	\$1,011.00	—
1PC	FRONT BUMPER PDC SENSOR O/S		111	\$185.00	X
1PC	FRONT BUMPER RADAR SENSOR O/S		SUC	\$850.00	X
1PC	HEADLAMP O/S	3200	CRU	\$3,300.00	—
1PC	WIPER WASHER TANK	168.50	DE	\$244.00	—
1PC	FRONT FENDER CRU O/S	416.00	D11	\$580.00	—
1PC	FRONT FENDER INNER SHIELD O/S	166.50	TOCN	\$248.00	—
1SET	FRONT FENDER INNER SHIELD CLIPS O/S		111	\$50.00	—
1PC	FRONT FENDER INNER SPONGE O/S	102.00	TOCN	\$221.00	—
1PC	FRONT FENDER INNER PANEL O/S		R	\$455.00	X
1PC	FRONT SHOCK ABSORBER O/S	392.50	BUNT	\$580.00	—
1PC	FRONT SHOCK ABSORBER TOP MOUNTING O/S	180.40	TWI	\$190.00	—
1PC	FRONT LOWER ARM O/S	455.30	SUC	\$788.00	—
1PC	FRONT KNUCKLE ARM O/S	376	BUNT	\$745.00	—
1PC	FRONT KNUCKLE ARM BEARING O/S		111	\$280.00	—
1PC	FRONT STEERING RACK ASSY	2255.30	BUNT/TM	\$3,250.00	—
1PC	FRONT STEERING CROSS MEMBER	2080.20	BUNT/TM	\$2,250.00	—
1PC	FRONT DRIVE SHAFT O/S		SUC	\$1,650.00	X
1PC	FRONT DOOR O/S	1127.50	BODY	\$1,215.00	—
2PCS	FRONT DOOR HINGE O/S @\$105.00		BUNT	\$210.00	—
1PC	FRONT DOOR CHECKER O/S		TWI	\$148.00	—
1PC	FRONT DOOR INNER RUBBER O/S	168.50	111	\$199.00	—
1PC	FRONT DOOR INNER TRIM BOARD O/S	611.20	DE/TM	\$988.00	—
1SET	FRONT DOOR INNER TRIM BOARD CLIPS O/S		111	\$50.00	—
1PC	FRONT DOOR GLASS REGULATOR O/S	380	BUNT	\$399.00	—
1PC	FRONT DOOR OUTER PILLAR O/S		R	\$845.00	X
1PC	FRONT DOOR INNER LOCK O/S	262.30	SHU	\$488.00	—
1SET	FRONT DOOR FRAME BLACK STICKER O/S		111	\$85.00	—
1PC	REAR DOOR O/S	954.10	D11/BUNT	\$1,105.00	—
1PC	REAR DOOR INNER RUBBER O/S	168.50	111	\$195.00	—
1PC	REAR DOOR INNER LOCK O/S		SUC	\$488.00	X
1PC	REAR DOOR INNER TRIM BOARD O/S	605.30	TOCN	\$950.00	—
1SET	REAR DOOR INNER TRIM BOARD CLIPS O/S		111	\$50.00	—
1PC	REAR FENDER O/S		R	\$1,105.00	X
1PC	REAR FENDER UNDER SHIELD O/S		111	\$182.00	X

202

1PC	REAR WHEEL HUB BEARING O/S	Dange	520	\$620.00	/
1PC	REAR TRAILING ARM O/S	su		\$845.00	X
1PC	REAR SHOCK ABSORBER O/S	twl	292.40	\$305.00	/
1PC	REAR BUMPER	n		\$1,021.00	X
1PC	REAR BUMPER SIDE RETAINER O/S	11		\$66.00	X
1SET	REAR BUMPER CLIPS	11		\$50.00	X
1PC	TAILLAMP O/S	11		\$985.00	X
1PC	ROCKER PANEL O/S	10/30/1	(202)	608.30	\$850.00
1PC	ROCKER PANEL GARNISH O/S	70/11		620.00	\$855.00
1SET	ROCKER PANEL GARNISH CLIPS O/S	11		\$50.00	/
				\$34,514.00	
1PC	front sport rim O/S	\$ 450	s/n	werped	/
1PC	Rear sport rim O/S	\$ 450	s/n	werped	/

TO CHECK WIRING		\$50.00	20
TO DISMANTLE & REFIX ^{front} REAR PDC SENSOR		\$80.00	50
TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$120.00	80
TO DISMANTLE & REFIX REAR WINDSCREEN	11	\$120.00	X
TO DISMANTLE & REFIX O/S DOOR MECHANISM		\$120.00	/
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE		\$200.00	120
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE		\$500.00	350
TO CONDUCT WHEEL ALIGNMENT		\$120.00	80
TO DIAGNOSTIC & REPROGRAMME SYSTEM		\$500.00	300
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$2,200.00	1200
TO PUTTY & SPRAY PAINTING		\$2,000.00	1600
TOTAL		\$40,524.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

19095.01
202
15276.08
900
3920
20296.08
202
16076.