

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details				Customer Details			
THIRD PARTY CLAIM				Account No.	M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
				S1000020 / TPCLAIM			
				Document No. 0			
				Document Date 07/06/2022			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	21/04/2017	SLN0637Y	0	15583	66TP/SLN0637Y/070622
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU803556067		2ZRS038758	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:XD6782G ACC DATE:07/06/22 DRIVE IN:07/06/22 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50	100.00
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST				180.00	
3	B	BP-LAB2 TRANSFER BOOTLID MECHANISM AND REVERSE C AMERA				540.00	
4	B	BP-LAB2 REPL REAR WINDSCREEN AND FIXED GLASS				720.00	
5	B	BP-LAB2 R/I INTERIOR TRIMMING TO FAC REPAIR (pht)				360.00	
6	B	BP-LAB2 VACCUM SHATTERED GLASS				180.00	
7	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SESNOR				180.00	
8	Z	BP-BKT SUPPLY PHV STICKER				20.00	
9	Z	BP-SLANT SUPPLY SEALANT (NETT)2 PANEL				160.00	
10	S	BP-SUBLET RESET ECU UPON COMPLETION OF REPAIR				180.00	
11	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL 720 X 2 STRAIGHTEN AND REALIGN ACC AFF AREA 590 X 2				3600.00	
12	B	BP-RES2 RESRPAY ACC AFF AREA				2950.00	
13	1	TREVSE-TEFM2 070 2PT R SENSOR WITH ANGLE 070 WH 1 / BR	1.00	101.05		101.05	
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company							Amount Due

Acknowledged by Repairer

Signature:

Date:

Company Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd				
		Document No. 0	6 Battery Road #38-04 Singapore 049909				
		Document Date 07/06/2022	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	21/04/2017	SLN0637Y	0	15583	66TP/SLN0637Y/070622
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU803556067		2ZRS038758	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
14	2	U52023-47030	REINFORCEMENT	1.00	353.10		353.10
15	3	U52576-47040	RETAINER, RR BUMPER	1.00	123.60		123.60
16	4	U52575-47040	RETAINER, RR BUMPER	1.00	124.90		124.90
17	5	U52159-47913	COVER, RR BUMPER	1.00	469.50		469.50
18	6	U52453-47010	GUARD, RR BUMPER,	1.00	611.30		611.30
19	7	S52161-0K040	PIECE, RR BUMPER	4.00	4.30		17.20
20	8	U58307-47090	PANEL SUB-ASSY, BODY	1.00	689.70		689.70
21	9	U64716-47130 C0	COVER, DECK TRIM, RR	1.00	134.30		134.30
22	0	U64993-47110	BOX, DECK FLOOR, RR	1.00	112.30		112.30
23	1	U56117-50140	DAM, WINDOW GLASS	1.00	30.60		30.60
24	2	U68105-47291	GLASS SUB-ASSY, BACK	1.00	1758.70		1758.70
25	3	U62267-47010	DAM, SIDE WINDOW	1.00	6.30		6.30
26	4	T21000-20	SIKA 182010 SIKA TACK GO! (BLA	3.00	108.00		324.00
27	5	T21000-22	SIKA 207. G+P ADHESIVE PRIMER	2.00	200.00		400.00
28	6	U67881-47051	WEATHERSTRIP, BACK	1.00	394.70		394.70
29	7	U67005-47540	PANEL SUB-ASSY, BACK	1.00	1216.40		1216.40
30	8	U76801-47110 A1	GARNISH SUB-ASSY,	1.00	984.40		984.40
31	9	U67750-47080 C0	BOARD ASSY, BACK	1.00	274.70		274.70
32	0	U69350-47050	LOCK ASSY, BACK DOOR	1.00	495.40		495.40
33	1	U75403-48010	EMBLEM SUB-ASSY,	1.00	76.00		76.00
For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd							
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
						Amount Due	

Company Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd				
		Document No. 0	6 Battery Road #38-04 Singapore 049909				
		Document Date 07/06/2022	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	21/04/2017	SLN0637Y	0	15583	66TP/SLN0637Y/070622
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU803556067	2ZRS038758	60	Shashitharan	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
34	2	U75441-47130 PLATE, LUGGAGE COMPT	1.00	58.00		58.00 ✓	
35	3	U75442-47130 PLATE, LUGGAGE COMPT	1.00	58.00		58.00 ✓	
36	4	U76085-47916 SPOILER SUB-ASSY, RR	1.00	1668.60		1668.60	
37	5	U81551-47283 LENS & BODY, RR	1.00	479.30		479.30	
38	6	U81561-47153 LENS & BODY, RR	1.00	469.90		469.90	
39	7	U81581-47011 LENS & BODY, RR	1.00	532.00		532.00	
40	8	U81591-47011 LENS & BODY, RR	1.00	532.00		532.00	
41	9	U81204-47010 LAMP SUB-ASSY, X	1.00	305.30		305.30	
Supp - Glass Sub-Assy, Back ✓ BR \$805.50 (Stem CLKK) ✓ 9/6/22, 2.39pm PIP ✓ RL 5 dgr							
For & on behalf of		Customer's Signature	Charge Summary		Total	21,971.25	
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts	12,801.25	GST 7.00%	1,537.99	
			Labour	8,990.00	Less	0.00	
			Sublet	180.00			
			Lubrication/Fluid	0.00			
			Others	0.00	Amount Due	23,509.24	

Company Copy