

Vehicle Damage Assessment Report for [SLM4644E]

Estimate Created: 09/06/2022 07:14 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 01/08/2022 23:25 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Lexus	Model	ES
Engine Type			
License Plate Number	SLM4644E	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provided by LKK: Recommended cost of repair at \$3633.99 with 4 days for repair

Insurlogic 1 (01/08/2022 23:23)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
TAIL LAMP RH		1	926.60	-10.00 %	833.94
REAR BUMPER		1	986.90	-10.00 %	888.21
REAR BUMPER CLIPS		1	52.00	-10.00 %	46.80
REAR BUMPER RETAINER RH		1	122.20	-10.00 %	109.98
REAR BUMPER SIDE BRACKET CLIPS RH		1	6.30	-10.00 %	5.67
REAR BUMPER TOP RETAINER RH		1	118.60	-10.00 %	106.74
REAR BUMPER STAY BRACKET RH		1	158.50	-10.00 %	142.65

Parts Subtotal 2,133.99

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
CHECK WIRING	RnR	20.00	0.00 %	20.00
REMOVE AND REFIX INTERIOR TRIMMING AND GARNISH	RnR	80.00	0.00 %	80.00
WHEEL ALIGNMENT AND BALANCING	RnR	60.00	0.00 %	60.00
DIAGNOSTIC	RnR	60.00	0.00 %	60.00
REPLACE REAR BUMPER AND TAILLAMP	RnR	250.00	0.00 %	250.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
REAR FENDER RH	Unknown	350.00	0.00 %	350.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
REAR BUMPER	Full spray	250.00	0.00 %	250.00
REAR FENDER RH	Full spray	250.00	0.00 %	250.00
REAR FENDER INNER RH	Full spray	180.00	0.00 %	180.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 820.00

Paint Labor Subtotal 680.00

Labor Subtotal 1,500.00

Summary

Repair Cost 3,633.99

Discount(0 %)	(0.00)
	3,633.99
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	3,633.99