哈汽車貿易服務

HUP MOTOR TRADING & SERVICE Email: hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: http://hupmotor.com.sg Reg. No. 378091/00W

Our Ref: TP 3069/06/22

Your Ref:

Date: 23rd June 2022

0

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
64, Cecil Street, #05-00, IOB Bldg.
Singapore 049711

Dear Sirs,

RE: ACCIDENT ON 05/06/22 ALONG JALAN RENGKAM
INVOLVING: SLM 4644 E & YOUR INSURED: SLS 2960 Z

We act for Mr Lim Zi Ping., NRIC No: S8316916H
Who is the registered owner of Veh. No: SLM 4644 E Which was involved in the above accident with Veh. No: SLS 2960 Z Which we understand is insured with you.

Your appointed surveyor had surveyed our client's damaged vehicle and we had repaired the vehicle.

The accident was clearly caused by your insured's negligence, I am, therefore, seeking compensation from you for my financial losses as itemised below: -

Cost of repair

Loss of Use for 4 days (1 day X \$ 120.00)

LTA Search Fee

Survey Fee

\$ 3,633.99

480.00

0.00

\$ 4,113.99

We have enclosed copies of relevant documents to support my client's claim, There was no receipt enclosed, as my client's did not pay us any single amount.

Your prompt settlement of our claim would be much appreciated.

Yours faithfully,

HUP MOTOR TRADING & SERVICE

Mr David Ang B. Y.

Encl: Final Bill, Car Rental Bill, LTA Search Fee, Owner Authorisation Letter, GIA Report, Survey Report & Ins. Cert.



TO: M/S INDIA INTERNATIONAL INSURANCE PTE. LTD.

AUTHORIZATION TO ACT

I, MR LIM ZI PING (S8316916H) ("the third party claimant")
of BLK 248, #04-414, HOUGANG AVE 3, S(530248) (address),
owner of SLM 4644 E (vehicle no.) hereby authorize
Hup Motor Trading & Service,
("The workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my
Vehicle No. SIM 4644 E that was damaged pursuant to the
accident which occurred on 05/06/22 (date) along Jalan
Rengkam (location)
involving Vehicle No/s SLS 2960 Z (Your Insured)
("The accident").
I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.
I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.
Dated this 20th day of June (month) 20 22 (year) HUP MOTOR TRADING & SERVICE Mr Lim Zi Ping (S8316916H)
Signed by "the third party claimant" Signed by "the workshop"



INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792k | GST. Reg. No. M2-0078806-X 64 | Cecil Street | #04 | #05 | #06-02 | IOB Building | Singapore 049711

Office (65) 63476100 E Fax (65) 62244174 V

("the workshop") hereby confirm that we/I have reached an agreement

Email insure@iii.com.sg Website www.iii.com.sg

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MPC2022D0002959 Claimant Ref: SLM 4644E

We/I, HUP MOTOR TRADING & SERVICE

	Surveyor of India International Insurance Pte Ltd LK espect to the amount claimed for S\$ 3,633.99					
use/rental), S\$	- (search fee), vehicle no. SLM 4644E that was	damaged pursua	int to the accident which occurred			
on 5/6/2022	(date) at Jln Rengkam	(location) involv	ving vehicle no. SLS 2960Z (insured			
vehicle). This is purs	suant to the inspection conducted on 09/06/2022 (da	ite) at "the workshop)".			
	we/I are/am authorized by the owner LIM ZI	***************************************	("the third party			
	le no. SLM 4644E to make the claim as set out in the					
party claimant".	ner behalf in a manner that we/l deem fit. We/l end	nose nerem me re	tter of authority given by the third			
party Claimant.						
We/I further confirm	n that we/l will indemnify India International Insuran	ce Pte Ltd for all o	damages, loss and/or expense that			
they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a						
further claim again	nst the former for any loss and expenses suffered p	pertaining to cost of	of repairs and/or rental and/or loss			
of use pursuant to	the damage to SLM 4644E (vehicle no.) as a result	of the accident.				
	the agreement reached above is in full and final s					
basis.	cident and that further this settlement is reached on	a without prejudic	e and without admission of nability			
This agreement is	subject to the application of Singapore law and the S	Singapore Courts h	nave exclusive jurisdiction over any			
dispute arising out	of the same.					
We/l authorize yo	outopaythe total amount of S\$ 4,033.99 to HU	JP MOTOR TRADI	NG & SERVICE .			
Dated this 3rd	day of August 20 22					
	HUP MOTOR TRADING & SERVICE					
CLAIMANT:		WITNESS:	· ((LKK))			
Signature:	Lasteches and a construction of the constructi	Signature:	\\/ / cks			
	Signed by "the workshop" (with chop)		Signed by appointed Surveyor			
Name:	Signed by "the workshop" (with chop) Hup Motor Trading & Service	Name:	LKK AUTO CONSULTANTS PTE LTD			
Name: NRIC:		Name: NRIC:				
NRIC:	Hup Motor Trading & Service	NRIC:	LKK AUTO CONSULTANTS PTE LTD 199607198R			
	Hup Motor Trading & Service 37809100-W		LKK AUTO CONSULTANTS PTE LTD 199607198R 51 UBI AVE 1 #02-25			
NRIC:	Hup Motor Trading & Service 37809100-W BLK 9004, #01-120, Tampines	NRIC:	LKK AUTO CONSULTANTS PTE LTD 199607198R			
NRIC:	Hup Motor Trading & Service 37809100-W BLK 9004, #01-120, Tampines	NRIC:	LKK AUTO CONSULTANTS PTE LTD 199607198R 51 UBI AVE 1 #02-25			

哈汽車貿易服務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref:	TP 3069/06/22 Your Ref: Date: 23	rd J	une 2022	
	M/S INDIA INTERNATIONAL INSURANCE PTE. LTD. 64, Cecil Street, #05-00, IOB Bldg. Singapore 049711			
	Invoice for Cost of repair to TOYOTA LEXUS (A) 2.5 Salo	on -	SIM 4644	E
	1 pc o/s tail lamp assy 1 pc rear bumper 10 pcs rear bumper clips 2 \$ 5.20 N 1 pc rear bumper o/s side retainer 1 pc rear bumper o/s side bracket clips 1 pc rear bumper o/s top retainer 1 pc rear bumper o/s stay bracket		926.60 986.90 52.00 122.20 6.30 118.60 158.50	**
	Less 10%		2,371.10 237.11	Nett
		\$	2,133.99	
	To wiring check up for affected wiring system.		20.00	
	To remove & refix carpet, floor mat, garnish, cushion seafloor board cover, rear o/s fender inner shield & necessaparts.	at,	80.00	
	To check & adjust wheel alignment & balancing.		60.00	
	To diagnose & re-set tail light & reverse sensor fault co	de.		
5	Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear o/s fender & necessary parto weld, renew & align above parts.	ts,	600.00	
•	To putty & respray painting on all affected accident part	s.	680.00	
		\$	3,633.99	

Dollars: Three Thousand Six Hundred Thirty Three And Cents Ninety Nine Only.

HUP MOTOR TRADING & SERVICE

8/3/22, 10:02 AM Merimen e-Claims

Print Received Message

This mail is associated with:

*SLM4644E (MPC2022D0002959) [SLS2960Z] TP LIM ZI PING Jun 5 2022 11:00PM [-]

Hup Motor Trading & Service

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 02/08/2022 09:05 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4033.99) - SLM4644E - Claim Handler: Gabriel Wee

Approved:4033.99.