

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLM4644E
at Workshop m/s hugauto-
of _____
Insured: SL52960E
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 4108k.
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

916h
Vehicle: IN / OUT

Date: _____ Person Contacted: LTA 88045

Veh No: SLM4644E Yr Regn: 31/03/17
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA /
Make: Lexus ES 300h c.c. 2494
Colour: Black A/C: Insured / Std / NI / NA
Sp.Reading: 127227 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JTHBW166802147248
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/55R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front 6 mm Rear 6 mm
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 05/06/22 D.O.I. 9/6/22
Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Rep 18k.

No second hand parts repairer said to owner want All new parts

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
Date/Time, File Return to?

2) _____

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

) \$ + RS \$
) Photos
) Others

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

哈, 汽車貿易服務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 37809100W

Our Ref: TP 3069/06/22

Your Ref:

Date: 7th JUNE 2022

MR LIM ZI PING
BLK 248, #04-414
HOUGANG AVE 3, S(530248)

*Not a Motor
all
P16/22
4 days
Warranty before going
by H/C*

Estimate cost of repair to TOYOTA LEXUS (A) 2.5 Es300h Saloon - SLN 4644 E

1 pc o/s tail lamp assy		one \$	926.60	Nett
2 pcs o/s tail lamp clips stopper	11	\$ 6.80 N	13.60	" X
1 pc rear bumper		to m	986.90	"
10 pcs rear bumper clips	11	\$ 5.20 N	52.00	"
1 pc rear bumper o/s side retainer		one	122.20	"
1 pc rear bumper o/s side bracket clips		11	6.30	"
1 pc rear bumper o/s top retainer		11	118.60	"
1 pc rear bumper sponge damper		11	137.80	" X
1 pc rear bumper o/s reflector		11	60.40	" X
1 pc rear o/s fender		1	1,197.10	" X
8 pcs rear o/s fender inner shield clips	6	\$ 5.90 N	47.20	" X
1 pc rear windscreen glass outer moulding		11	78.60	" X
1 pc rear windscreen glass inner dam rubber		11	48.80	" X
1 pc rear windscreen glass sealant		11	60.00	" X

Less 10% \$ 3,856.10 Nett
\$ 385.61

\$ 3,470.49

To wiring check up for affected wiring system.	50.00	20
To remove & refix rear windscreen glass & necessary parts.	150.00	
To remove & refix carpet, floor mat, garnish, floor board cover, fender inner shield, cushion seat & necessary parts.	150.00	80
To check & adjust wheel alignment & balancing.	150.00	60
To diagnose & re-set tail light & reverse sensor fault code.	150.00	60
To respray Tuff-Kote on all affected accident parts.	11 90.00	X
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts. -	1,300.00	600
To putty & respray painting on all affected accident parts.	1,350.00	680

\$ 6,860.49
=====

Dollars : Six Thousand Eight Hundred Sixty And Cents Forty Nine Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 916H

Vehicle Details

Vehicle No.: SLM4644E
Vehicle to be Exported: No
Intended Deregistration Date: 09 Jun 2022
Vehicle Make: TOYOTA
Vehicle Model: LEXUS ES300H EXECUTIVE CVT S/R
Primary Colour: Black
Manufacturing Year: 2017
Engine No.: 2AR1647292
Chassis No.: JTHBW1GG802147248
Maximum Power Output: 151.0 kW (202 bhp)
Open Market Value: \$42,522.00
Original Registration Date: 31 Mar 2017
First Registration Date: 31 Mar 2017
Transfer Count: 1
Actual ARF Paid: \$46,531.00 13265

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 Mar 2027
PARF Rebate Amount: \$32,571.00

Intended COE Rebate Details

COE Expiry Date: 30 Mar 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$53,001.00
COE Rebate Amount: \$25,474.00
Total Rebate Amount: \$58,045.00

The information contained herein is correct as at 09 Jun 2022

OK