

車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

ampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Ref: TP 3069/06/22

Your Ref:

Date: 7th JUNE 2022

MR LIM ZI PING
BLK 248, #04-414
HOUGANG AVE 3, S(530248)

2/2 \$3633.99

Not Allowed
all
P/6/22
4 days
light before going
by H/S

Nett item

Estimate cost of repair to TOYOTA LEXUS (A) 2.5 Es300h Saloon - SLM 4644 E

1 pc o/s tail lamp assy	Cne \$	926.60	Nett
2 pcs o/s tail lamp clips stopper	11 @ \$ 6.80	13.60	" X
1 pc rear bumper	Tom	986.90	"
10 pcs rear bumper clips	ner @ \$ 5.20	52.00	"
1 pc rear bumper o/s side retainer	cne	122.20	"
1 pc rear bumper o/s side bracket clips	ner	6.30	"
1 pc rear bumper o/s top retainer	3er	118.60	"
1 pc rear bumper sponge damper	17	137.80	" X
1 pc rear bumper o/s reflector	3u	60.40	" X
1 pc rear o/s fender	1	1,197.10	" X
8 pcs rear o/s fender inner shield clips	@ \$ 5.90	47.20	" X
1 pc rear windscreen glass outer moulding	1A	78.60	" X
1 pc rear windscreen glass inner dam rubber	17	48.80	" X
1 pc rear windscreen glass sealant	17	60.00	" X

\$ 3,856.10 Nett

Less 10% \$ 385.61

\$ 3,470.49

To wiring check up for affected wiring system.

50.00 20

To remove & refix rear windscreen glass & necessary parts.

11 150.00 X

To remove & refix carpet, floor mat, garnish, floor board cover, fender inner shield, cushion seat & necessary parts.

150.00 80

To check & adjust wheel alignment & balancing.

150.00 60

To diagnose & re-set tail light & reverse sensor fault code.

150.00 60

To respray Tuff-Kote on all affected accident parts.

11 90.00 X

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts. -

1,300.00 600

To putty & respray painting on all affected accident parts.

1,350.00 680

\$ 6,860.49

=====

Dollars : Six Thousand Eight Hundred Sixty And Cents Forty Nine Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-2371-1

1-2133-99

2-1800

3633 99