## 哈汽車貿易服務

#### HUP MOTOR TRADING & SERVICE Email: hu

Email: hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: http://hupmotor.com.sg Reg. No. 378091/00W

O Dafe	TP	3069/06/22	Vous Defe	Data	23rd June 2022
Our Ret:		J	Your Ref:	Date:	

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
64, Cecil Street, #05-00, IOB Bldg.
Singapore 049711

Dear Sirs,

RE: ACCIDENT ON 05/06/22 ALONG JALAN RENGKAM
INVOLVING: SLM 4644 E & YOUR INSURED: SLS 2960 Z

We act for Mr Lim Zi Ping., NRIC No: S8316916H
Who is the registered owner of Veh. No: SLM 4644 E Which was involved in the above accident with Veh. No: SLS 2960 Z Which we understand is insured with you.

Your appointed surveyor had surveyed our client's damaged vehicle and we had repaired the vehicle.

The accident was clearly caused by your insured's negligence, I am, therefore, seeking compensation from you for my financial losses as itemised below: -

Survey Fee			\$ 4,113.99
LTA Search Fee			0.00 0.00
Cost of repair Loss of Use for 4	days ( 1	day X \$ 120.00 )	\$ 3,633.99 480.00

We have enclosed copies of relevant documents to support my client's claim, There was no receipt enclosed, as my client's did not pay us any single amount.

Your prompt settlement of our claim would be much appreciated.

Yours faithfully,

HUP MOTOR TRADING & SERVICE

Mr David Ang B. Y.

Encl: Final Bill, Car Rental Bill, LTA Search Fee, Owner Authorisation Letter, GIA Report, Survey Report & Ins. Cert.

# 哈汽車貿易服務

### **HUP MOTOR TRADING & SERVICE**

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref:	TP 3069/06/22 Your Ref: Date:	Ju	ne 2022	
	M/S INDIA INTERNATIONAL INSURANCE PTE. LTD. 64, Cecil Street, #05-00, IOB Bldg. Singapore 049711			
	Invoice for Cost of repair to TOYOTA LEXUS (A) 2.5 Saloon		SIM 4644	E
	1 pc o/s tail lamp assy 1 pc rear bumper 10 pcs rear bumper clips \$ 5.20 N 1 pc rear bumper o/s side retainer 1 pc rear bumper o/s side bracket clips 1 pc rear bumper o/s top retainer 1 pc rear bumper o/s stay bracket	•	926.60 986.90 52.00 122.20 6.30 118.60 158.50	11 11 11
		\$	2,371.10 237.11	Nett
		\$	2,133.99	
	To wiring check up for affected wiring system.		20.00	
	To remove & refix carpet, floor mat, garnish, cushion seat, floor board cover, rear o/s fender inner shield & necessary parts.		80.00	
	To check & adjust wheel alignment & balancing.		60.00	
	To diagnose & re-set tail light & reverse sensor fault code	L.	60.00	
	Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear o/s fender & necessary parts to weld, renew & align above parts.	,	600.00	
	To putty & respray painting on all affected accident parts.		680.00	
		\$	3,633.99	

Dollars: Three Thousand Six Hundred Thirty Three And Cents Ninety Nine Only.

HUP MOTOR TRADING & SERVICE



TO: M/S INDIA INTERNATIONAL INSURANCE PTE. LTD.

## AUTHORIZATION TO ACT

I, MR LIM ZI PING (S8316916H) ("the third party claimant")
of BEK 248, #04-414, HOUGANG AVE 3, S(530248) (address),
owner of SLM 4644 E (vehicle no.) hereby authorize  Hup Motor Trading & Service,
("The workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my
Vehicle No. SLN 4644 E that was damaged pursuant to the
accident which occurred on 05/06/22 (date) along Jalan
Rengkam (location)
involving Vehicle No/s SLS 2960 Z (Your Insured)
("The accident").
I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.
I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.
Dated this 20th day of June (month) 20 22 (year)  HUP MOTOR TRADING & SERVICE
Mr Lim Zi Ping (S8316916H)