

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 202222005088KC Date: 29th July 2022

Our Ref: CS6/AIS22005501/Gqy3m4

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01 Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SLQ 2277Z ACCIDENT ON 31/05/2022

We thank you for your instruction on 09/06/2022.

The following vehicle information was recorded:

Registration Number : SLQ 2277Z

Make & Model : Mercedes Benz CLA180 SB URBAN (R18 LED)

Chassis Number : WDD1179422N496420

Year of Registration : 2017 Engine Capacity : 1595 cc

- 1. The vehicle sustained damages at the front portion. (Details see photographs enclosed)
- 2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.