

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte.
Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan Kian Chuan

Date: 10 Jun 2022

Preliminary Advice

Vehicle No	: SLQ2277Z	Accident Date	: 31/05/2022
Make	: MERCEDES-BENZ C180	Policy No.	: SP2000435666
Assignment Date	: 09/06/2022	Excess	: S\$1,000.00
Date of Inspection	: 10/06/2022	Est. Duration of Repair	: 3
Inspection At	: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 11,624.20
Revised Amount	:S\$ 2,855.32
Check Items (Estimated)	:S\$ 8,128.88
Total	:S\$ 10,984.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 101,000.00
COE / PARF Rebate	:S\$ 49,991.00

Salvage Value	:S\$
Margin for Repair	:S\$ 51,009.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.