



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLQ2277Z

Mr Lim

36 Countryside Road
Singapore 789802

Mobile: +6596363306

Vehicle & Document Information

WIP No 57440
Reg No/Reg Date SLQ2277Z / 31/07/2017
Date In/Mileage / 0
Chassis No WDD1179422N496420
Engine No 27091031251980
Make/Model MB/MB CLA 180 S/B (X117) "FACELIFT"
Colour/Trim 027 787 Mountain Gr/ 041 151 Lther ARTIC

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	09/06/2022/ 11:53	VS	356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE :SP2000435666-01 //								
DRIVE IN/EXCESS : 09.06.2022 //								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
M BPNSUN								
SUNDRIES								15.00
A BPILAB							0.10	380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								
A BPILAB								120.00
TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT								
A BPILAB								1200.00
PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH								
A BPIRES								1200.00
RESPRAY ON FRONT BUMPER AND ACCIDENT AFFECTED AREA								
M FRONT BUMPER ?					1.00	1433.30	00.00	1433.30
M COMPANY SIGN ?					1.00	65.25	00.00	65.25
M RADAR SENSOR ?					1.00	1233.72	00.00	1233.72
M IMPACT ABSORBER ?					1.00	184.71	00.00	184.71
M TOP BASIC MOUNTING FOR BUMPER ?					1.00	183.05	00.00	183.05
M RH TOP BASIC MOUNTING FOR BUMPER ?					1.00	33.83	00.00	33.83
M RHF SIDE STABILITY ?					1.00	66.57	00.00	66.57
M RHF MOUNTING RAIL ?					1.00	15.36	00.00	15.36
M RIGHT AIR FLOW SERRATION ?					1.00	80.80	00.00	80.80
M LEFT AIR FLOW SERRATION ?					1.00	70.96	00.00	70.96
M FRAME SEGMENT-RADIATOR GRILLE ✓ CRA					1.00	295.45	00.00	295.45
M STAR CARRIER HOUSING-SILVER ✓ CRA					1.00	180.79	00.00	180.79
M MERCEDES STAR CARRIER ✓ CRA					1.00	81.30	00.00	81.30
M MERCEDES STAR ✓ MIS					1.00	142.78	00.00	142.78

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLQ2277Z

Mr Lim

36 Countryside Road
Singapore 789802

Mobile: +6596363306

Vehicle & Document Information

WIP No **57440**
Reg No/Reg Date **SLQ2277Z / 31/07/2017**
Date In/Mileage **0**
Chassis No **WDD1179422N496420**
Engine No **27091031251980**
Make/Model **MB/MB CLA 180 S/B (X117) "FACELIFT"**
Colour/Trim **027 787 Mountain Gr/ 041 151 Lther ARTIC**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	09/06/2022/ 11:53	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M CENTRAL RIGHT TRIM SRIP ?	1.00	81.96	00.00	81.96
M CENTRAL LEFT TRIM SRIP ?	1.00	81.96	00.00	81.96
M RIGHT HEADLAMP UNIT ?	1.00	3099.15	00.00	3099.15
M FRONT SUPPORT PANEL ?	1.00	1027.99	00.00	1027.99
M CROSS MEMBER ?	1.00	350.27	00.00	350.27

ESTIMATE

3 Days
Before paint photos
After repair photos
Excess: TBA
Not Authorised
Guo Qiang - LKK
HP: 82880282
GuoQiang@lkkauto.com
10/06/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirmed & accepted by

7% GST on **Nett 11,624.20**
813.69

Authorized signatory and company stamp

Total Payable 12,437.89

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg