



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SLQ2277Z

Mr Lim

Allianz Insurance Singapore Pte  
79 Robinson Rd #09-01  
Singapore 068898

### Vehicle & Document Information

WIP No 57440  
Reg No/Reg Date SLQ2277Z / 31/07/2017  
Date In/Mileage 15/06/2022/ 63515  
Chassis No WDD1179422N496420  
Engine No 27091031251980  
Make/Model MB/MB CLA 180 S/B (X117) "FACELIFT"  
Colour/Trim 027 787 Mountain Gr/ 041 151 Lther ARTIC

Account No	Terms	Date/Time Printed	CSE	Operator	
CTP00001	Cash	21/06/2022/ 17:48		356 / Vincent Seah	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request  
M BPNUN

POLICY NO/ACC DATE : SP2000435666-01 // 31.05.2022  
DRIVE IN/EXCESS : 09.06.2022 // \$1000  
DATE IN/DATE SURVEY: // 10.06.2022 paper survey- GUAQIANG-LKK  
BY/AUTHORIZED ON : SHIAU CHAN-LKK // 13.06.2022

M BPNUN

SUNDRIES

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO  
IDENTIFICATION STANDARD. NETT

A BPILAB

PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW  
BODY PANELS WITH REFINISH.

A BPIRES

RESPRAY ON FRONT BUMPER AND ACCIDENT AFFECTED AREA

X FRAME SEGMENT-RADIATOR GRILLE

X STAR CARRIER HOUSING-SILVER

X MERCEDES STAR CARRIER

X MERCEDES STAR

X BPNEXC

INSURANCE EXCESS

15.00

0.10

380.00

960.00

0.05

800.00

1.00

295.45

00.00

295.45

1.00

180.79

00.00

180.79

1.00

81.30

00.00

81.30

1.00

142.78

00.00

142.78

-1000.00

Finalization

Confirmed & accepted by

Nett 1,855.32  
7% GST on 1855.32 129.87

Authorized signatory and company stamp

Total Payable 1,985.19

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG