LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI22005504/RQY3E2

02/08/2022 Date:

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle SHB765X Insured Vehicle No: XB7677G No:

Date of Loss: 07/06/2022 Nature of Claim: ΤP Claim No: CDMCG22001096

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB765X**

TOYOTA PRIUS, 1.8 (A) Make & Model: Engine No: 2ZR1461874

Reg. Date: 10/12/2014 (Man. Year: 2014) Chassis No: JTDKN36U305753496

Colour: Odometer: Maroon 0 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Sailun 6 mm Front Left Side: Rear Left Side: Sailun 6 mm Front Right Side: Sailun 6 mm Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,210.10	899.40	3,310.70	78.64
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,734.00	620.00	1,114.00	64.24
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,944.10	1,519.40	4,424.70	74.44
	Approved Total (Overridden) (S\$)		300.00		
	Nett Amount (S\$)	5,944.10	300.00	5,644.10	94.95

INSPECTION

09/06/2022 Date of Assignment:

Strides Automotive Services Pte Ltd (Woodlands) 09/06/2022 Inspected At: Date Inspected:

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Aug 2022)

Parts: 144 TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB765X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR FRT/RH (DISC 25%)	Bent	894.40 F	*670.80 F
2	1		*STICKER STRIDES TAXI (DOOR) (SN)	Necessary	60.00 F	*60.00 F
3	1		*HINGE LOWER RHF, DOOR	Not Necessary	90.10 F	*-F
4	1		*HINGE UPPER RHF, DOOR	Not Necessary	80.50 F	*- F
5	1		*CHECK ASSY, FR DOOR	Not Necessary	150.30 F	*- F
6	1		*DOOR BELT FRT/RH	Not Necessary	69.20 F	*- F
7	1		*DOOR REGULATOR SUB-ASSY, FRT / REAR RH	Not Necessary	224.80 F	*-F
8	1		*DOOR REGULATOR MOTOR FRONT RH	Not Necessary	947.80 F	*- F
9	1		*MOULDING, FR DOOR WINDOW RH	Not Necessary	53.70 F	*- F
10	1		*MIRROR ASSY, RH	Not Necessary	1,307.10 F	*- F
11	1		*COVER, OUTER MIRROR, RH	Repair	107.40 F	*- F
12	1		*DOOR REGULATOR SUB-ASSY, FRT/REAR RH (DISC 25%)	Bent	224.80 F	*168.60 F
F=Fra	nchise	part.				
				Total Parts (S\$)	4,210.10	899.40
			Report was unsubmitted during this print-or	ıt		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING AND BODY WORK	New	676.00	250.00
2	SPRAY PAINT	New	558.00	270.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	40.00
6	TO TRANSFER DOOR MECHANISM	New	120.00	60.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
		Gross Labour Cost (S\$)	1,734.00	620.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.