

SIN HWEE MOTOR PTD LTD

BLK 3023A UBI RD 1 #01-59

SINGAPORE 408717

UEN: 201327079M

Estimate

Date	Estimate #
7/6/2022	1006

Name / Address
NG KIN CHOY

VEHICLE NO	MODEL
SJG 9140 P	MIT LANCER

Description	Qty	Rate	Total
REAR FENDER - NETT		689.11	689.11
LESS 10%		0.00	0.00
SPORT RIM		550.00	550.00
1 PC REAR BUMPER		650.00	650.00
TO REPLACE REAR FENDER INCLUDE KNOCKING, HEATING AND CUTTING		1,200.00	1,200.00
TO REPLACE AND ALIGN REAR BUMPER			
REMOVE AND REFIX WINDSCREEN		180.00	180.00
WINDSCREEN SEALANT		100.00	100.00
TO SPRAY PAINT REAR FENDER, REAR DOOR AND REAR BUMPER		900.00	900.00
COMPUTERIZED ALIGNMENT		80.00	80.00

Thwgn@LKH auto.com
82235769
10/6/22 1345
L/S 4 days w/p
F: 2030
pp. 4

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
Acknowledged by Repairer Signature: Date:	

Total

\$4,349.11