

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST: 201300201N

**M/S :** CHINA TAIPING INSURANCE (SINGAPORE) PTE  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

TEL: 63896111

FAX: 62247175

ATTN: Motor Claim Department

**Estimate No:** EST2200182

Date: 08 Jun 2022

Veh Reg No: SLH3005H

Make/Model: BMW X1 SDRIVE 18I M  
SPORT AT LED NAV

Chasis No: WBAHS120605F02420

Reg. Date: 28/10/2016

Your Ref No: GBF3347A

Claim Type: Third Party

Accident Date: 30/05/2022

TP Veh Reg No: GBF3347A

*Xiao Tony*

## Estimate Repair Cost to Vehicle No :SLH3005H

| Quantity | Description                                                                                                   | List Price | Amount   |
|----------|---------------------------------------------------------------------------------------------------------------|------------|----------|
|          |                                                                                                               | SS         | SS       |
|          | <b>List Price</b>                                                                                             |            |          |
| 1        | 1 PC FRT BUMPER <i>Rebond</i>                                                                                 | 1,327.45   |          |
| 2        | 1 PC FRT BUMPER SIDE RETAINER LH <i>m</i>                                                                     | 75.10      |          |
| 3        | 1 PC FRT FENDER PROTECTOR LH <i>Repair</i>                                                                    | 315.70     | X        |
| 4        | 1 PC FRT BUMPER PARKING SENSORS LH <i>Rebond</i>                                                              | 286.80     | ✓        |
| 5        | 1 PC HEADLAMP LH <i>cut</i>                                                                                   | 2,728.95   | ✓        |
| 6        | 1 PC FRT FOG LAMP LH                                                                                          | 366.90     | X        |
| 7        | 1 PC FRT FOG LAMP COVER LH <i>3mm</i>                                                                         | 102.10     | X        |
|          |                                                                                                               | 5,203.00   |          |
|          | Less 5%                                                                                                       | 260.15     | 4,942.87 |
|          | <b>Special Net</b>                                                                                            |            |          |
| 8        | 1 SET FRT BUMPER CLIPS <i>Reu</i>                                                                             | 60.00      | 30       |
| 9        | 1 PC FRT BUMPER PROTECTOR CLIPS <i>Reu</i>                                                                    | 40.00      | 20       |
|          |                                                                                                               | 100.00     | 100.00   |
|          | <b>Labour</b>                                                                                                 |            |          |
| 10       | 1 TO CHECK WIRING                                                                                             | 50.00      | 30       |
| 11       | 1 (FRONT) TO SPRAY PAINTING                                                                                   | 450.00     | 350      |
| 12       | 1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. | 500.00     | 350      |
| 13       | 1 TO PROGRAM                                                                                                  | 300.00     | 120      |
|          |                                                                                                               | 1,300.00   | 1,300.00 |

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

TEL: 63896111 FAX: 62247175  
ATTN: Motor Claim Department

Claim Type: Third Party  
Accident Date: 30/05/2022  
TP Veh Reg No: GBF3347A

Estimate No: EST2200182

Date: 08 Jun 2022

Veh Reg No: SLH3005H

Make/Model: BMW X1 SDRIVE 18I M  
SPORT AT LED NAV

Chasis No: WBAHS120605F02420

Reg. Date: 28/10/2016

Your Ref No: GBF3347A


## Estimate Repair Cost to Vehicle No :SLH3005H

| Quantity | Description | List Price<br>S\$    | Amount<br>S\$ |
|----------|-------------|----------------------|---------------|
|          |             | Total                | S\$ 6,342.87  |
|          |             | Add GST @ 7%         | 444.00        |
|          |             | Total Amount Payable | S\$ 6,786.87  |

TOTAL: SINGAPORE DOLLAR SIX THOUSAND SEVEN HUNDRED EIGHTY SIX AND CENTS  
EIGHTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time  
which may be required after work has begun.

For Kang Car Repairers Pte Ltd

  
AUTHORISED SIGNATURE

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj  
4/5 08/06/22  
03 Pays.

total 4856.47

4/5: 3850

~~3850~~

3850