

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL: 62715133, 62717433 FAX: 62745715

ESTIMATE REPAIR

Allianz Insurance Singapore Pte Ltd

Pg1

Date: 9.6.2022

Owner's Name : Ong Sze Chuan

Vehicle No : SNC4082E

Vehicle Make & Model : Honda Civic 1.6 VTI CVT

Claim Type: Third Party Claim

Chassis No: MRHFC5650KT000676

Registration Date : 5 Oct 2019 (YOM 2019) COE Expiry Date 3 Oct 2029

DOA: 8.6.2022

No	Description	Unit	List (\$)
1	REAR BOOT / <i>00</i>	1	\$ <i>580</i> 780.00
2	REAR BOOT OUTER / <i>BR</i>	1	\$ <i>110</i> 220.00
3	REAR BOOT EMBLEM / <i>nc</i>	1	\$ 60.00
4	REAR BOOT "CIVIC" / <i>nc</i>	1	\$ 85.00
5	REAR BOOT "I-VTEC" / <i>nc</i>	1	\$ 95.00
6	REAR BOOT LOCK <i>x nn</i>	1	\$ 268.00
7	REAR BOOT HINGE <i>x nn</i>	2	\$ 180.00
8	REAR BOOT HINGE COVER <i>x nn</i>	2	\$ 150.00
9	REAR BOOT LIGHT <i>x nn</i>	2	\$ 370.00
10	REAR LH LAMP / <i>BR</i>	1	\$ 320.00
11	REAR RH LAMP <i>x nn</i>	1	\$ 320.00
12	REAR LAMP CLIPS <i>x nn</i>	2	\$ 12.00
13	REAR BUMPER / <i>BR</i>	1	\$ 680.00
14	REAR BUMPER LOWER WITH CHROME / <i>CVT</i>	2	\$ 365.00
15	REAR BUMPER TOW COVER / <i>CVT</i>	1	\$ 45.00
16	REAR BUMPER SIDE RETAINER (LH) / <i>BR</i>	<i>21</i>	\$ 120.00
17	REAR LH BUMPER REFLECTOR GARNISH <i>x nn</i>	1	\$ 145.00
18	REAR LH BUMPER REFLECTOR <i>x nn</i>	1	\$ 110.00
19	REAR BUMPER SENSOR / <i>BR</i>	<i>x 1</i>	\$ 880.00
20	REAR BUMPER SENSOR SEAL / <i>nc</i>	SET	\$ 60.00
21	REAR END PANEL <i>BR (phd) x R</i>	1	\$ 520.00
22	REAR END PANEL TOP GARNISH <i>x nn</i>	1	\$ 180.00
23	REAR RUBBER / <i>CR4</i>	1	\$ 175.00

2805
-20%
2244

Total (A): \$ 6,140.00
Less 20% \$ 1,228.00
Total: \$ 4,912.00

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL: 62715133 62717433 FAX: 62745715

ESTIMATE REPAIR

Pg2

Allianz Insurance Singapore Pte Ltd

Date: 9.6.2022

Owner's Name : Ong Sze Chuan

Vehicle No : SNC4082E

Claim Type: Third Party Claim

Vehicle Make & Model : Honda Civic 1.6 VTi CVT

Chassis No: MRHFC5650KT000676

Registration Date : 5 Oct 2019 (YOM 2019) COE Expiry Date 3 Oct 2029

DOA: 8.6.2022

No	Description	Unit	List (\$)
Special Nett			
1	CAR PLATE NUMBER WITH HOLDER X <i>nn</i>	SET	\$ 50.00
2	REAR BUMPER CLIPS <i>/ M</i>	SET	\$ <i>30 /</i> 40.00
3	REAR LH & RH FENDER SHIELD CLIPS X <i>nn</i>	2 SET	\$ 60.00
4	REAR INNER TRIM BOARD/COMPARTMENT CLIPS X <i>nn</i>	SET	\$ 50.00
Labour			
1	Spray Painting to All Affected Areas	1	\$ 800.00 ✓
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	1	\$ <i>900</i> 1,000.00 <i>800 /</i>
3	Anti Rust Treatment	1	\$ <i>30 /</i> 100.00
4	To Remove / Refix/Replace Reverse Sensor	1	\$ <i>30 /</i> 180.00
5	To Remove/Refix Rear Reverse Camera	1	\$ <i>50 /</i> 150.00
6	To Remove/Refix Inner Compartment & Carpet To Facilitate Repair	1	\$ <i>80 /</i> 280.00
7	Computer Disgnosis After Repair	1	\$ <i>70 /</i> 350.00
<i>Stete (LKK) M ML</i>			<i>1860</i>
<i>10/6/22, 2.3p P/P</i>			
<i>hy PL y</i>			<i>Total - 4134</i>
<i>5 djs</i>			
Total (B):			\$ 3,060.00
Grand Total:			\$ 7,972.00