

Block 1008 Bukit Merah Lane 3 #01-04
Singapore 159722

vehicle No	YQ3538K	Date	24-Nov-22
Make / Model	MIT FUSO FM65FM6RDEA	Branch	15 FAN YOONG ROAD
Year of Mfg	2020	Fax No	6264 3151
Chassis No	FM65FMA40064	Tel No	8717 3377

No	Qty	Description & Specification	Cost Price	TOTAL	
1		RADIATOR FAN BLADE	440	440.00	✓ BR
2	2	BRACKET ,RAD SUPPORT LH/RH	25	50.00	✓ BT
3		RADIATOR FAN CLUTCH	2750	2750.00	✓ Jammed
4		RADIATOR SHROUD,SEAL	170	170.00	✓ CUT
5		RADIATOR RING FAN SHROUD	405	405.00	✓ CUT
6		TURBO INTERCOOLER HOSE INLET	363	170.00	✓ BT
7		TURBO INTERCOOLER HOSE OUTLET	302	302.00	✓ BT
8		TURBO INTERCOOLER HOSE OUTLET CONNECTION	305	305.00	✓ BT
9		AIRCON HOSE PIPING (COMPRESSOR) IN	420	420.00	✓ BT
10		AIRCON HOSE PIPING (COMPRESSOR) OUT	525	525.00	✓ BT
11		AIRCON CONDENSER FAN SHROUD	180	180.00	✓ BR
12		AIR CLEANER RESONATOR	55	55.00	✓ MIS
13		ENGINE ROOM COVER RH	163	163.00	✓ BR
14		ENGINE ROOM COVER LH	220	220.00	✓ BR
15		FRONT BUMPER	870	870.00	X Repair
16		FOG LAMP RH	160	160.00	X Reuse
		COST TOTAL		7185.00	
		15% COST PLUS		1077.75	
		TOTAL PARTS		8262.75	
		LABOUR			
1		TO REMOVE AND REPLACE TURBO INTERCOOLER, RADIATOR,		200.00	100 ✓
		RADIATOR FAN CLUTCH & FAN BLADE			
		TOTAL LABOUR		200.00	
		NON TAX AMOUNT		8462.75	
		GST 7%		592.39	
		AMOUNT DUE		9055.14	