



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD
#02-01 UOI BUILDINGSINGAPORE 068909

Ref: CS/UOI22005519/Evy3e2

Date: 30/06/2022

Code: UOI2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	PC 2424S
Policy No.	DHOM110166501903	Coverage (\$)	0.00
Claim No.	M11D15432206	Excess (\$)	750.00
Assign From	JOSEPHINE WONG	Assign Date	10/06/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTFST22P600018743	Colour	WHITE
Odometer	396121 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	DUNLOP	4 mm
L/H Front Tyre	195 R15C	DUNLOP	4 mm
R/H Rear Tyre	195 R15C	DUNLOP	4 mm
L/H Rear Tyre	195 R15C	DUNLOP	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/06/2022	Inspection Date	10/06/2022
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A)THE MARKET VALUE IS S\$30,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.