

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

YN 5744J
OD/Sompo

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE

Claim No: ES2290577

#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

Date: 10 Jun 2022
Policy No: D21MTPCVE001791

TEL: 64616555

FAX: 62213302

Veh Reg No: YN5744J

ATTN: Motor Claim Department

Make/Model: MITSUBISHI MIT.

NOT Authorize

CANTER

11 Reg &

FEB21ER3SDEB

WS Ref:

OD/SOMPO

Chassis No: FEB21EA00702

Claim Type:

Own Damage

Engine No: 4P10B30337

Accident Date:

01/06/2022

Reg. Date: 31/07/2014

Pushing the Pain
12 days

Estimate Repair Cost to Vehicle No : YN5744J

Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 FRONT BUMPER	500.00	1 PC	500.00	✓
2 FRONT BUMPER RH BRACKET	110.00	1 PC	110.00	✓
3 FRONT BUMPER RH SIDE PAD	220.00	1 PC	220.00	✓
4 RH HEADLAMP	290.00	1 PC	290.00	✓
5 RH SIGNAL LAMP	170.00	1 PC	170.00	✓
6 RH HEADLAMP SIDE REFLECTOR	105.00	1 PC	105.00	✓
7 FRONT GRILLE	550.00	1 PC	550.00	✓
8 FRONT PANEL EMBLEM (FUSO)	70.00	1 PC	70.00	✓
9 FRONT WIPER GARNISH	180.00	1 PC	180.00	✓
10 FRONT PANEL (BIG)	1,200.00	1 PC	1,200.00	✓
11 FRONT RH CORNAL PANEL	270.00	1 PC	270.00	✓
12 AIRCON EVAPORATOR	980.00	1 PC	980.00	✓
13 AIR-CON GAS DISCHARGE HOSE	155.00	1 PC	155.00	✓
14 FRONT WINDSCREEN GLASS RUBBER	190.00	1 PC	190.00	✓
				4,990.00
Special Net				
15 FRONT NUMBER PLATE	35.00	1 PC	35.00	2012 35.00
Labour				
16 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1 LA	100.00	✓
17 REMOVE AND REFIX AIRCON, CHARGE VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
18 REMOVE & REFIX DASHBOARD, METER ASSY	280.00	1 LA	280.00	250
19 PANEL BEATING AND STRAIGHTEN FRT RH WIND/SCREEN PILLAR	800.00	1 LA	800.00	700
20 PUTTY AND RESPRAY ON FRT PANEL, CORNAL PANEL, FRT GRILLE, FRT RH WS PILLAR, FRT RH DOOR, FRT BUMPER, CABIN RR PAN EL	800.00	1 LA	800.00	720
21 TO REMOVE ALUMINIUM CANOPY & ATTACHMENT, SUPPLY 1 SET ASSY FRT WOODEN STRUCTURE, FRT STRUCTURE BOARD AND INSTALLATION	1,700.00	1 LA	1,700.00	1400
22 REMOVE ALUMINIUM CANOPY & ATTACHMENT; SUPPLY 2 SIDE SLIDING CANVAS, FRT WINDOW GLASS, 4 PCS PILLAR, 1 PC REAR ROLL DOWN CANVAS AND 1 SET ROOF TOP STRUCTURE ASSY	3,800.00	1 LA	3,800.00	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Total

7,580.00

Add GST @ 7%

882.35

Total Amount payable

S\$ 13,487.35

For Cheng Hoe Motor Pte Ltd