

Huey Yon (LKKAUTO)

From: Huey Yon (LKKAUTO)
Sent: Monday, 15 August 2022 10:14 AM
To: 'chmotor@singnet.com.sg'
Cc: SUR
Subject: RE: YN 5744J OD SOMPO
Attachments: YN 5744J-Supp.pdf

Dear Sir/Madam,

Please proceed the supplementary as attached with our surveyor marking.

Best Regards,

Huey Yon | case handler
LKK Auto Consultants Pte.Ltd.
Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Monday, 13 June 2022 9:31 AM
To: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: YN 5744J OD SOMPO

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **YN 5744J (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)