

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI22005525/TNY3Q2**Date:** 11/04/2023**REFERENCE**

Insured/Claimant:	NG YAO GUANG	Policy No:	DMPF21011518	
Date of Loss:	07/06/2022	Nature of Claim:	OD	Claim No: CDMPG22001086

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP2702G		
Make & Model:	KIA CERATO, 1.6 SUNROOF (A)	Engine No:	G4FGKH749811
Reg. Date:	19/09/2019 (Man. Year: 2019)	Chassis No:	KNAF5416ML5054619
Colour:	White	Odometer:	41466 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$87,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,739.00	1,232.00	1,507.00	55.02
Miscellaneous Items	580.00	524.00	56.00	9.66
Labour	990.00	700.00	290.00	29.29
Paintwork Labour	600.00	500.00	100.00	16.67
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,909.00	2,956.00	1,953.00	39.78
Approved Total (Overridden) (\$\$)		2,350.00		
- Excess (\$\$)	0.00	500.00	-500.00	
(\$\$)	4,909.00	1,850.00	3,059.00	62.31
+ GST 7.00/8.00% (\$\$)	343.63	148.00	195.63	56.93
Nett Amount (\$\$)	5,252.63	1,998.00	3,254.63	61.96

INSPECTION

Date of Assignment:	10/06/2022 Present Location:	Woon Meng Motor Pte Ltd (Bukit Batok)
Date Inspected:	10/06/2022 Inspected At:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building Singapore 659578
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2023)
Parts:	143	KIA CERATO 1.6 SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP2702G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER O/S (WCP)	Bent	185.00 F	*185.00 F
2	2		*FRONT KNUCKLR ARM (WCP)	Bent	390.00 F	*390.00 F
3	2		*LOWER ARM (WCP)	Bent	360.00 F	*360.00 F
4	1		*STEERING RACK (WCP)	Not Necessary	400.00 F	*- F
5	1		*WHEEL BEARING (WCP)	Necessary	185.00 F	*185.00 F
6	2		*FRONT ABSOBER MOUNTING (WCP)	Not Necessary	170.00 F	*- F
7	1		*CROSSMEMBER (WCP)	Not Necessary	500.00 F	*- F
8	2		*FRONT SHOCK ABSOBER (WCP)	Not Necessary	300.00 F	*- F
F=Franchise part.						
Sub Total (\$\$)					2,490.00	1,120.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					249.00	112.00
Total Parts (\$\$)					2,739.00	1,232.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	TYRE (80%) (CUT)	280.00	224.00
2	1	TYRE RIM O/S (CRACKED)	300.00	300.00
Sub Total (S\$)			580.00	524.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO PUTTY & SPRAY PAINTING	New	600.00	500.00
Labour Items				
2	TOWING FEE	New	70.00	70.00
3	TO REMOVE, REPLACE, REPAIR, INSTALL & WELD DAMAGED PARTS	New	450.00	400.00
4	TO R & R UNDERCARRIAGE	New	350.00	150.00
5	TO WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (S\$)			1,590.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >