

Woon Meng Motor Pte Ltd (Co.Reg.No:200603678M)

50 Bukit Batok Street 23,, #01-06 Midview Building

Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

INSURER:

ERGO Insurance Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPF21011518	Date of Loss:	07/06/2022
Vehicle Reg. No.:	SMP2702G	Driveable?	
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG YAO GUANG	Contact No:	+6596185578
Driver:	NG YAO GUANG		

Make/Model:	KIA CERATO, 1.6 SUNROOF (A)	Vehicle Reg. Date:	19/09/2019
Vehicle Colour:	WHITE		
Engine No:	G4FGKH749811	Chassis No:	KNAF5416ML5054619
Odometer:	41466 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	8

Present Location:	WOON MENG MOTOR PTE LTD (BUKIT BATOK)
-------------------	---------------------------------------

COST OF CLAIMS	Amount
Parts	2,739.00
Miscellaneous Items	580.00
Labour	990.00
Paintwork Labour	600.00
Towing	0.00
Gross Total (\$\$)	4,909.00
+ GST 7.00% (\$\$)	343.63
Nett Amount (\$\$)	5,252.63

This claim is handled by: HENG SEW SOW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 10 Jun 2022)**Parts:** 143 KIA CERATO 1.6 SUNROOF (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Woon Meng Motor Pte Ltd/SMP2702G/10/06/2022 13:35**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER O/S	0.00	0.00	bt — *185.00 F
2	2		*FRONT KNUCKLR ARM	0.00	0.00	bt — *390.00 F
3	2		*LOWER ARM	0.00	0.00	bt — *360.00 F
4	1		*STEERING RACK	0.00	0.00	? *400.00 F
5	1		*WHEEL BEARING	0.00	0.00	wh — *185.00 F
6	2		*FRONT ABSOBER MOUNTING	0.00	0.00	? *170.00 F
7	1		*CROSSMEMBER	0.00	0.00	? *500.00 F
8	2		*FRONT SHOCK ABSOBER	0.00	0.00	? *300.00 F

F=Franchise part.

Sub Total (S\$)	2,490.00
+ Margin on L,N Items 10.00% (S\$)	249.00
Total Parts (S\$)	2,739.00

Woon Meng Motor Pte Ltd/SMP2702G/10/06/2022 13:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Parts: \$1120.00+10%= \$1232.00

Check: \$1370.00 + 10%= \$1507.00

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	TYRE			art 80% 280.00 200
2	1	TYRE RIM O/S	SN: 410.00		On 300.00 250
Sub Total (\$)					580.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1	TO PUTTY & SPRAY PAINTING	Painting: \$500.00	New	500	600.00
---	---------------------------	--------------------	-----	-----	--------

Labour Items

2	TOWING FEE		New	✓	70.00
3	TO REMOVE, REPLACE, REPAIR, INSTALL & WELD DAMAGED PARTS		New	400.	450.00
4	TO R & R UNDERCARRIAGE		New	150?	350.00
5	TO WHEEL ALIGNMENT		New	80 ✓	120.00

Labour: \$550.00

Gross Labour Cost (\$\$) 1,590.00

Check Labour: \$150.00

Woon Meng Motor Pte Ltd/SMP2702G/10/06/2022 13:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495747 / 62563561
Not Antuarise, Ravat
Ex \$500
p/p Resurvey before paint
10/6/22 @ 530pm
taufik @ lkkauto.com
04 days

Pre Review done base on survey information provided

Take note that this review is done before finalization, a final review on repair
cost to be concluded after repair.

Note: Please upload tyre size and model, check on cost price as well.

Pre Review By : Insurlogic

Amount : \$2692.00

Check: \$1657.00

Total: \$4349.00

Repair Duration: 4 days