



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22005531/Avy3m4 Date: 15/05/2023 Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 9665S	Veh. Inspected	SGY 8P	
Policy No.		Coverage (\$)	0.00	
Claim No.	M11D15482206	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	10/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ V300D	c.c	1950	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	W1V44781523685901	Colour	BLACK	
Odometer	36014 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50R18	PIRELLI	6 mm	
L/H Front Tyre	245/50R18	PIRELLI	6 mm	
R/H Rear Tyre	245/50R18	PIRELLI	6 mm	
L/H Rear Tyre	245/50R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/06/2022	Inspection Date	10/06/2022	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	