

Veron

Rasul survey on 13/6/2022



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SNE2359K Toyota RAIZE Newly PI model

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 1,206.00 ✓ DD
2	1	Rear bumper left bracket	\$ 88.00 XSK
3	1	Rear bumper right bracket	\$ 88.00 XSK
4	1	Rear bumper left retainer	\$ 98.00 CRA
5	1	Rear bumper right retainer	\$ 98.00 CRA
6	1	Rear side corner light-left (reflector)	\$ 250.00 XNN
7	1	Rear side corner light-right (-v)	\$ 250.00 CRA 125
8	1	Rear bumper tow cover	\$ 80.00 XNF
9	2	Bumper side cover -lower side wing RH	\$ 360.00 X CUT
10	1	Bumper lower lip	\$ 696.50 XNN
11	1	Tailgate middle trim	\$ 358.30 XNN
12	1	Rear middle trim logo	\$ 95.00 XNN
13	1	Rear end top garnish	\$ 376.30 CRA 235
14	1	Rear tailgate	\$ 1,580.00 CRA
15	1	Tailgate inner trim cover	\$ 625.60 TA 455
16	1	Rear tailgate emblem-Raize	\$ 120.00 NEC 58
17	1	Rear tailgate weatherstrip	\$ 375.80 BT 355
18	1	Rear boot lock mechanism	\$ 332.60 XNN
19	1	Boot lower lock cover	\$ 95.00 XNS
20	1	Pull pocket / on bonnet	\$ 88.00 XNN
21	1	Rear tailgate no plate lamp	\$ 170.00 CRA 65
22	1	Rear tailgate left taillamp	\$ 955.50 CRA 582
23	1	Rear tailgate right taillamp	\$ 955.50 CUT 582
24	1	Rear left taillamp	\$ 795.80 CRA 682
25	1	Rear right taillamp	\$ 795.80 CRA 682
26	2	Rear tailgate damper	\$ 560.00 XNN
27	1	Rear end lower panel	\$ 685.30 BUC
28	2	Edge Molding / rear panel side molding	\$ 300.00 DIS/CRA
29	1	Rear fender inner trim whole piece -left	\$ 785.00 DIS 580
30	1	Rear fender inner trim whole piece -right	\$ 785.00 DIS 580
31	2	Tailgate inner side trim cover /corner trim cover RH	\$ 330.00 X CRA
32	2	Tailgate inner square cover x2pc	\$ 160.00 XNN
33	1	Keyless sensor	\$ 285.50 XNN
34	2	Rear end vent	\$ 180.00 DF
35	1	Reverse cam with wiring	\$ 580.00 CRA 350
36	1	Spare tyre top cover	\$ 650.00 CRA 525
		Parts Sub-total	\$ 16,234.50



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SNE2359K Toyota RAIZE Newly PI model

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips	\$ 80.00 30 NEC
2	10	Rear end lower lip garnish clips	\$ 60.00 20 NEC
3	1	Rear end lower panel sealant	\$ 100.00 30 NEC
4	20	Rear tailgate inner trim board clips	\$ 80.00 20 NEC
5	10	Rear tailgate outer garnish clips	\$ 50.00 10 NEC
6	10	Rear fender and light clips	\$ 60.00 X NN
7	8	Tarilgate midle trim clips	\$ 60.00 10 NEC
8	10	Lower lip clips	\$ 80.00 X NN
9	1	Rear windscreen glass sealant	\$ 80.00 50 NEC
10	1	Rear windscreen mounding <i>less 25%</i>	\$ 240.00 NEC 192
11	1	Rear no plate with garnish	\$ 45 100.00 DD
12	1	Windscreen seal	\$ 250.00 50 NEC
13	2	Rerve sensor <i>less 25%</i>	\$ 500.00 CUT 380
		Special nett	\$ 1,740.00



Xin Yun Auto Private Limited
 幸运汽车服务有限公司
 Tel: 6634 0858 Email: xinyunauto1@gmail.com
 Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SNE2359K
 Modle: TOYOTA RAIZE

No	Description	Labour Charges	
1	Checking rear wiring harness and lighting system for proper function	\$ 80.00	30
2	Carry up body cavity preservation for affected area \$50 per panel	\$ 200.00	80
3	Replacing accident damages parts, knock, jack and straighten accident damages area	\$ 1,600.00	900
4	Spray painting for accident affected damaged area, including: Tailgate in & out, bumper, lower lip, rear end panel, spare tyre area, both fender touch up	\$ 1,800.00	1000
5	To replacing rear undercarriage parts, including brake bleeding brake system etc.	\$ 120.00	X
6	Carry out wheel alignment	\$ 120.00	X
7	Removing and installing rear bootlid compartment garnish, trimming etc, to facilitate the necessary repair.	\$ 150.00	60
8	Transferring tailgate /bootlid lock mechanisam, trimming etc to the new tailgate /bootlid	\$ 120.00	60
9	Removing and installing rear exhaust muffler assy to facilitate the repair	\$ 150.00	X
10	Checking central lock system for proper function	\$ 120.00	X
11	Removing and installing rear fender internal garnish and training to facilitate the necessary repair	\$ 120.00	50
12	Removing and installing rear last row 2 seats and seatbelt to facilitate the necessary repair	\$ 350.00	X
13	Programming and coding	\$ 350.00	120
14	Removing and installing rear window /windscreen glass	\$ 150.00	120
15	To remove and install rear camera	\$ 80.00	50
16	Transferring tailgate and rear end wiring harness for proper function	\$ 150.00	X
17	Water test after accident repair body work	\$ 120.00	X
18	Paint protection coating for accident affected areas	\$ 350.00	X
19	Carry out diagnosis check including cleaning accident fault code	\$ 150.00	X
Total labour :		\$ 6,280.00	

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: