



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 7196E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER COVER REAR UP (SN)	DEFORMED	1,865.70	1,679.13
1	BUMPER COVER LOWER R (SN)	DEFORMED	1,865.70	1,679.13
1	PROTECTOR PLATE SLI (SN)	DEFORMED	666.40	599.76
1	ABSORBER (SN)	NOT NECESSARY	228.60	-
1	BUMPER SECTION REAR (SN)	NOT NECESSARY	364.30	-
10	BUMPER EXPANSION PLU (SN)	NECESSARY	88.00	79.20
1	LID (SN)	NOT NECESSARY	44.00	-
10	PLASTIC RIVET P/W RA (SN)	NECESSARY	101.00	90.90
10	BUMPER CLIP 8X8 ,5 (SN)	NECESSARY	82.00	73.80
10	BLIND RIVET 4.0 *21 P (SN)	NECESSARY	50.00	45.00
10	CLIP BRACKET BUMPER (SN)	NECESSARY	73.00	65.70
4	PARK ASSIST REAR XC9 (SN)	NOT NECESSARY	3,719.60	-
1	V031201885/SILENCER (SN)	NOT NECESSARY	1,560.70	-
1	BUMPER INSTALLING MT (SN)	NECESSARY	101.40	91.26
			10,810.40	4,403.88
<b>LABOUR</b>				
	TO REPLACE REAR BUMPER ,REAR LOWER SPOILER ,REAR SKID PLATE, ETC.		2,550.00	850.00
	TO PUTTY SPRAY PAINT ON REAR BUMPER ETC.		1,700.00	750.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		555.00	555.00
			4,805.00	2,155.00
<b>GRAND TOTAL</b>			<b>15,615.40</b>	<b>6,558.88</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>6,558.88</b>

Report Ref No. CS/SMO22005537/Aqy3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.