



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOW GARNET			Ref: CS/ASM22005539/Rncm4 Date: 05/08/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 5886H	Veh. Inspected	SLZ 7212E	
Policy No.		Coverage (\$)	0.00	
Claim No.	S2M043W6	Excess (\$)	0.00	
Assign From	LOW GARNET	Assign Date	10/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY 2.0 A	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MR053DK5100112979	Colour	GREY	
Odometer	53976 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/06/2022	Inspection Date	13/06/2022	
Survey held at	J & E AUTOMOBILE SERVICES 9002 TAMPINES INDUSTRIAL PARK A #01-44 SINGAPORE 528836			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	