

J & E Automobile Services

Blk 9002, Tampines Street 93, #01-44, Tampines Industrial Park A S(528836)

Business Reg No: 53309545W
Tel: 6783 2909/ Fax:
E-Mail: chautomobile@yahoo.com.sg

To: Motor Claims Department

Date: 10/06/2022

Vehicle No: SLZ7212E Model: Toyota Camry
Date of Accident: 09/06/2022 @ 12:00hrs / Location: Blk 34, Whampoa West Carpark
Damaged Area: Front Right Side Portion

Estimated Repair Cost For SLZ7212E (Toyota Camry)

QTY	Parts	Amount
1	Front bumper <i>See</i>	\$ 1,108.20
1	Front bumper side retainer o/s <i>? X</i>	\$ 98.60 <i>X</i>
1	Front bumper bracket o/s <i>? X</i>	\$ 94.20 <i>X</i>
1	Front bumper sponge <i>X</i>	\$ 283.50 <i>X</i>
1	Front bumper reinforcement <i>X</i>	\$ 427.90 <i>X</i>
1	Front bumper centre air-grille <i>? de</i>	\$ 198.50
1	Front bumper chrome <i>cut</i>	\$ 228.20
1	Front bumper side garnish o/s <i>cut</i>	\$ 155.20
1	Front bumper fog lamp o/s <i>X</i>	\$ 266.90 <i>X</i>
1	Front bumper angle sensor o/s <i>See</i>	\$ 385.50 <i>S/N 200</i>
1	Headlamp assy W/Chrome garnish o/s <i>See</i>	\$ 2,221.70
1	Headlamp lower bracket o/s <i>? X</i>	\$ 112.20 <i>X</i>
1	Headlamp top support panel o/s <i>repair</i>	\$ 201.70 <i>X</i>
1	Radiator grille <i>? CR</i>	\$ 599.10
1	Radiator grille logo <i>? X</i>	\$ 72.80 <i>X</i>
1	Radiator grille top centre garnish <i>de</i>	\$ 296.80
1	Bonnet assy <i>bt</i>	\$ 1,347.20
1	Bonnet chrome <i>? X</i>	\$ 170.40 <i>X</i>
1	Support panel <i>X</i>	\$ 613.40 <i>X</i>
1	Front fender o/s <i>See</i>	\$ 961.40
1	Front fender emblem o/s <i>See</i>	\$ 68.50
1	Front fender inner shield o/s <i>? X</i>	\$ 196.20 <i>X</i>
1	Front door o/s <i>X</i>	

S/N-200

Parts Sum:	\$ 10,108.10	<i>7184.80</i>
Parts Less 25%:	\$ 2,527.02	<i>259</i>
Parts Total:	\$ 7,581.07	<i>5388.60</i>

Special Nett Items

1	Front bumper clips <i>See</i>
1	Radiator grille clips <i>See</i>
1	Radiator grille top garnish clips
1	Front fender inner shield clips
1	Front number plate w/garnish

<i>100</i>	\$ 68.00 <i>30</i>
	\$ 30.00 <i>20</i>
	\$ 20.00 <i>10</i>
	\$ 60.00 <i>30</i>
	\$ 55.00 <i>X</i>

Special Nett Items Total: \$ 225.00

Labour & Misc Charges

Description	Amount
To Remove, Replace, Re-align & Install affected Damaged Areas (\$300.00 per day)	\$ 1,200.00 <i>700</i>
To Putty, Prep & Re-spray on affected Damaged Areas (\$300.00 per panel) (Frt Door, Ctr Door Pillar, Front Fender, Front Bumper, Bonnet, Support Panel)	\$ 1,500.00 <i>700</i>
To Remove, Install, Condenser and Charge up AC Gas	\$ 120.00 <i>X</i>

To Remove & Install Radiator Assy, Conduct Pressure Test to Check For Leakage.

To Remove & Re-connect all electrical wirings to Facilitate Repairs

To Re-set Engine Management Fault-Code & Re-Programme (Calibration Angle Sensor, Focus Headlamp)

To Apply Undercoating on the Affected Damaged Areas

\$	120.00	Xm
\$	60.00	30
\$	250.00	100
\$	250.00	80

Labour Charges Total: \$ 3,500.00

Parts Total: \$ 7,581.07

Special Nett Items Total: \$ 225.00

Labour Charges Total: \$ 3,500.00

Total Cost Of Repair: \$ 11,306.07

(Non-Inclusive of GST)

1610

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue

Hp 90010068

6 days

L/S

13/06/22 P1545

Resue after repair

5388.60

200.00

100.00

1610.00

7298.60

20%

5838.88

L/S - \$5,800

6 days