

ASS. REC. BY:

REF:

A/S / 22 0055401K

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

(Client's Record) Excess: _____

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 018k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3-6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 03/24 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKX 8215M Yr Regn: 03, 09Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy A/TN C.C. 1598Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 329868 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR0 538 EE 106141692

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: Mobile 195/65R15R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 3 mm

Rear

R/Bal. 6 mmL/Bal. 3 mmL/Bal. 6 mmD.O.A. 9/8/22D.O.I. 14/6/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

Massive Trading & Auto

Blk 5034 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/ 91082728

Fax : 64816131

Sim Chooi Ploh
Blk 745 Woodlands Circle
#03-740
Singapore 730745

Vehicle No : SKX 8215 M
Make : Toyota Altis
Year : 2009

Not Notified
21 Sep 8
Painting After Rain
5-6 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front o/s fender	<i>R1</i>	\$497.10 ✓
1 pc	Front o/s fender innershield	<i>R2</i>	\$175.20 X
1 pc	Front o/s fender emblem	<i>na</i>	\$40.10 X
1 pc	Front o/s door	<i>R1</i>	\$1,075.10 ✓
1 pc	Front o/s door protector	<i>R1</i>	\$187.20 ✓
1 pc	Front o/s door view mirror		\$550.70 ?
1 pc	Front o/s door view mirror lamp	<i>cm</i>	\$176.20 ✓
1 pc	Front o/s door glass outer moulding	<i>R</i>	\$155.30 X
1 pc	Front o/s inner lock	<i>R</i>	\$325.10 X
1 pc	Front o/s door outer handle	<i>R</i>	\$165.20 X
1 pc	Front o/s door frame black sticker	<i>R</i>	\$65.70 ✓
1 pc	Front o/s door inner trim board		\$576.10 ?
1 pc	Front o/s door glass regulator		\$195.20 ?
1 pc	Front o/s door glass regulator motor		\$355.70 ?
1 pc	Front o/s door rubber	<i>R</i>	\$175.30 X
1 pc	Front o/s windscreen pillar	<i>R</i>	\$675.80 ?
1 pc	Front o/s windscreen pillar weatherstrip	<i>R</i>	\$205.30 X
2 pcs	Front o/s door hinge	<i>lower R1</i>	\$145.70
1 pc	Front o/s door checker		\$291.40 ✓
1 pc	O/S rocker panel garnish	<i>DIY</i>	\$105.10 ?
1 pc	Front windscreen glass moulding		\$687.10 ✓
1 pc	Rear o/s door protector	<i>R</i>	\$110.10 ?
		<i>R</i>	\$176.20 ✓
			\$6,966.20
		Less 25 %	\$1,741.55
			\$5,224.65

S Nett

1 pc Front windscreen sealant

\$40.00 ?

balance c/f \$5,132.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SKX 8215 M

balance b/f \$5,132.50

Labour Charges

Remove/renew the above parts including knocking and cutting etc.	\$1,000.00	700
To putty & spray paint front & rear accident affected portion.	\$1,000.00	800
Check/reconnect wiring.	\$40.00	200
To spray anti rust on accident affected portion.	\$150.00	600
Remove/refit front windscreen to facilitate repair.	\$120.00	7
Remove/refit roof lining to facilitate repair on rear fender	\$200.00	600
Remove/refit front dashboard to facilitate repair.	\$350.00	7
Total	<u>\$7,992.50</u>	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 10/06/2022 12:53 (SGT)
Date of Accident 09/06/2022 18:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information T junction of TELOK BLANGAH ROAD / BUKIT CHERMIN ROAD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKX8215M

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner SIM CHOOI PIOH
NRIC No S7581348A
Email Address MAGICCLOUD56@GMAIL.COM
Mobile Phone No (Phone) +65-91453603
Alternative Phone No +65-91453603

VEHICLE PARTICULARS

Manufacturer Toyota
Model Corolla
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 1600


INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5108330726-02
Cover Note Number -

DRIVER

Name of Driver SIM CHOOI PIOH
NRIC No S7581348A

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO GEARS REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 10/6/2022 1230

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: HONG DA

NRIC/FIN No.: S992334