

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0473/2022/JT
DATE : 8-Jun-22
WIP : 27741

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/6/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - Johnny Boo

11-Nov-22

OWNER'S NAME : MS TAN SIEW FOONG
ADDRESS : BLK 432 BUKIT PANJANG RING ROAD
#10-605
SINGAPORE 670432
TELEPHONE : HP +65 9126 5289
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220007934
VEHICLE NO : **SGQ 1219 H**
MODEL CODE : AUDI A3 SEDAN 1.5 TFSI
MODEL YEAR : 24/1/2022
ENGINE NO : DFY 293516
CHASSIS NO : WAUZZZGY2NA005888
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Jun-22
PLACE OF ACCIDENT : ADAM ROAD FOOD COURT CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGQ 1219 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER AND FRONT BUMPER LOWER SPOILER.	\$	1,500.00	\$ 850.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	3,572.00	\$ 2,022.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGQ 1219 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,677.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 290.00	
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 130.00	
4	FRONT BUMPER GRILLE - LOWER CENTER	1	\$ 433.00	\$ 346.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 265.00	
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 67.00	
7	FRONT BUMPER SPOILER	1	\$ 326.00	\$ 260.40
8	FRONT BUMPER TRIM COVER - RH	1	\$ 104.00	
9	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 171.00	
10	FRONT PARKING AID SENSOR SUPPORT - RH	1	\$ 43.00	
11	RADIATOR GRILLE	1	\$ 932.00	\$ 745.60
12	RADIATOR GRILLE CLOSING ELEMENT - CENTER	1	\$ 210.00	\$ 168.00
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 748.00	
14	FRONT BUMPER FOAM FILLER PIECE	1	\$ 120.00	
15	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 108.00	
16	FRONT BUMPER TOP COVER	1	\$ 93.00	
17	CAUTION STICKER	1	\$ 16.00	
18	AIR COND STICKER	1	\$ 9.00	
19	HORN - RH	1	\$ 161.00	
20	HORN SUPPORT - RH	1	\$ 35.00	
SUB TOTAL SPARE PARTS		:	\$ 5,938.00	\$ 1,520.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGQ 1219 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 1,520.00
21	HORN SUPPORT - UPPER	2	\$ 54.00	
22	FRONT PARKING AID SENSOR AIR GUIDE GRILLE - INNER / OUTER	2	\$ 558.00	
23	FRONT PARKING AID SENSOR SEAL RING	4	\$ 32.00	
24	HEADLIGHT - RH	1	\$ 4,084.00	
25	LIFT CYLINDER - RH	1	\$ 211.00	
26	LIFT CYLINDER HOSE	1	\$ 108.00	
27	RADIATOR AIR GUIDE	1	\$ 42.00	
28	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
29	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS			\$ 11,437.00	\$ 1,580.00
TOTAL LABOUR CHARGES			\$ 3,572.00	\$ 2,022.00
GRAND TOTAL			\$ 15,009.00	\$ 3,602.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-26/10/22



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT