

Vehicle Damage Assessment Report for [SLP3146S]

Estimate Created: 11/06/2022 09:35 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 22/07/2022 10:01 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	Vezel
Engine Type			
License Plate Number	SLP3146S	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Recommended cost of repair at lump sum \$4550.00 with 4 days for repair Insurlogic 1 (22/07/2022 09:59)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER		1	801.20	-20.00 %	640.96
FRONT BUMPER SIDE RETAINERS L/R		1	36.00	-20.00 %	28.80
FRONT BUMPER REINFORCEMENT		1	257.30	-20.00 %	205.84
RADIATOR GRILLE BASE		1	301.20	-20.00 %	240.96
RADIATOR GRILLE OUTER		1	202.90	-20.00 %	162.32
RADIATOR GRILLE LOGO		1	24.10	-20.00 %	19.28
RADIATOR GRILLE CHROME MOULDING		1	78.40	-20.00 %	62.72
HEADLAMPS L/R		2	1990.20	-20.00 %	3,184.32
HEADLAMP BRACKETS L/R		2	35.00	-20.00 %	56.00

Parts Subtotal 4,601.20

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER CLIPS		1.0	50.00	0.00 %	50.00
FRONT NUMBER PLATE		1.0	40.00	0.00 %	40.00

Materials Subtotal 90.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
CHECK WIRING	RnR	20.00	0.00 %	20.00
PANEL BEAT AND REPLACE DAMAGE ITEMS	RnR	400.00	0.00 %	400.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
FRONT AFFECTED AREA	Full spray	600.00	0.00 %	600.00

Labor Rate S\$ 50 / Hour General Labor Subtotal 420.00

Paint Labor Subtotal	600.00
Labor Subtotal	1,020.00

Summary

Repair Cost	5,711.20
Discount(20 %)	(1,161.20)
	4,550.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	4,550.00