

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

Estimate : ES708357

Date : 06/06/2022

Vehicle Num. : SLP 3146S

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 31/05/2022

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	FRONT BUMPER		927.50
2.	2PCS	FRONT BUMPER SIDE RETAINER	18.00	36.00
3.	1PC	FRONT BUMPER CENTER GRILLE		86.20
4.	1PC	FRONT BUMPER REINFORCEMENT		257.30
5.	1PC	FRONT BUMPER REINFORCEMENT MOULDING		35.00
6.	1PC	FRONT BUMPER LOWER GARNISH		212.70
7.	1PC	RADIATOR GRILLE BASE		301.20
8.	1PC	RADIATOR GRILLE OUTER		202.90
9.	1PC	RADIATOR GRILLE LOGO		24.10
10.	2PCS	RADIATOR GRILLE CHROME MOULDING	39.20	78.40
11.	2PCS	RADIATOR GRILLE SIDE BRACKET	19.00	38.00
12.	1PC	RADIATOR GRILLE CENTER BRACKET		42.10
13.	1PC	AMBIENT SENSOR		48.80
14.	2PCS	HEADLAMP	1,997.20	3,994.40
15.	2PCS	HEADLAMP LOWER BRACKET	35.00	70.00
16.	1PC	RADIATOR SUPPORT TOP GARNISH		56.10
17.	1PC	BONNET LOCK		80.60
List TotalS\$:				6,491.30
20.00% Discount S\$:				1,298.26
				5,193.04

CONTINUE / ...

5751.5

not Authorized
13/06/22
1/2 # 4550
taking into account
4 days.

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

Estimate : ES708357

Date : 06/06/2022

Vehicle Num. : SLP 3146S

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 31/05/2022

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1SET	SPECIAL NETT ITEMS :		
2.	1PC	FRONT BUMPER CLIP <i>Mer</i>		50.00 ✓
3.	1SET	FRONT NUMBER PLATE <i>Scr</i>		45.00 40
		RADIATOR SUPPORT TOP GARNISH CLIP <i>11</i>		30.00 X
		Special Nett Total S\$:		125.00
		LABOUR :		
		TO CHECK LIGHT SYSTEM AND WIRING	20	50.00
		ANTI-RUST AND BODY SEALANT	11	120.00 X
		TO VACCUM, REOIL AND REGAS AIR CON		
		LABOUR/PANEL BEATING, REPAIR BONNET AND SUPPORT PANEL	400	800.00
		SPRAY PAINTING 1)BUMPER 2)REINFORCEMENT 3)SUPPORT		
		4)BONNET 5)O/S FRT FENDER 6)N/S FRT FENDER	600	1,200.00
		Labour Total S\$:		2,170.00

E. & O.E.

Total S\$: 7,488.04

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-4601-20

S.N - 90

L-1020

5711.20

20%

4568