4/26/23, 4:01 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22005556/UPA3Q2

26/04/2023 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle SGY878U **Insured Vehicle No:** SJT7596C No:

Date of Loss: 27/05/2022 Nature of Claim: TP Claim No: 1543279218SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY878U**

MERCEDES-BENZ GLC 250, 2.0 4MATIC AMG Engine No: Make & Model: 27492031758891 LINE (R19 LED) (A)

16/12/2019 (Man. Year: 2019) WDC2533462F598674 Reg. Date: Chassis No:

72680 km Colour: Grey Odometer:

Engine Capacity: 1991 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Engine Modification: Handbrake (Serviceable): Yes No

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 255/55 R19 Front Left Side: Rear Left Side: Pirelli 7 mm Pirelli 7 mm Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,764.00	4,496.40	1,267.60	21.99
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,660.00	1,280.00	1,380.00	51.88
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,424.00	5,776.40	2,647.60	31.43
	Approved Total (Overridden) (S\$)		4,600.00		
	(S\$)	8,424.00	4,600.00	3,824.00	45.39
	+ GST 7.00/7.00% (S\$)	589.68	322.00	267.68	45.39
	Nett Amount (S\$)	9,013.68	4,922.00	4,091.68	45.39
	+ Car Rental (4.0 x S\$150.00/day + 7.00% GST) (S\$)		642.00		
		(S\$)	5,564.00		
	Liable Amount (50.00%) (S\$)		2,782.00		
	+ Doc/Search Fee (S\$)		2.00		
	Nett Liability (S\$)		2,784.00		
	Global Sum Settlement (S\$)		2,750.00		

INSPECTION

Date of Assignment: 13/06/2022

Falcon-Air Auto Services Pte Ltd (Tampines) Date Inspected: 13/06/2022 Inspected At:

Blk 9006 #01-200 Tampines St 93

Singapore

Estimated Period of Repair: 4.0 days Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*O/S FRONT WHEEL ARCH GARNISH	Grazed	321.00 FL	*321.00 FL	
2	1		*O/S FRONT FENDER	Repair	1,053.00 FL	*- FL	
3	1		*O/S FRONT DOOR	Dented / Bent	3,125.00 FL	*3,125.00 FL	
4	1		*O/S FRONT STEPBOARD GARNISH	Cut	1,561.00 FL	*1,350.00 FL	
5	10		*O/S FRONT WHEEL ARCH GARNISH CLIPS	Necessary	50.00 FS	*50.00 FS	
6	10		*O/S FRONT FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*-FS	
7	10		*O/S FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS	
8	10		*O/S FRONT DOOR RIVETS	Necessary	80.00 FS	*80.00 FS	
9	10	nort C=Cno	*O/S FRONT STEPBOARD GARNISH CLIPS	Not Necessary	80.00 FS	*-FS	
г-гіа	inchise	part. 5–5pcr	lett. L=ListItemDisc.	Sub Total (S\$)	6,370.00	4,976.00	
	- List Item Discount on L Items 10.00/10.00% (S\$)			606.00	479.60		
				Total Parts (S\$)	5,764.00	4,496.40	
	Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO TRANSFER DOOR GLASS }	New	150.00	80.00
2	TO TRANSFER DOOR MECHANISM }	New	150.00	0.00
3	TO REINITIALISE POWER WINDOW USING DIAGNOSTIC SCANNER }	New	280.00	100.00
4	TO CALIBRATE CENTRAL LOCKING USING DIAGNOSTIC SCANNER }	New	280.00	0.00
5	TO REPAIR INNER PANEL ACCIDENT DAMAGE AREA REPLACEMENT OF PARTS AND ALIGN THE SAME	New	800.00	400.00
6	TO PUTTY AND RESPRAY ACCIDENT DAMAGE AREA	New	1,000.00	700.00
	Gross Labour	r Cost (S\$)	2,660.00	1,280.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >