



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2204789

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 03/08/2022
Reference CC4/LPC22005557/Epa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. XD 8967C
Insured Veh. YN 8473X
Claim No. 21/22/22/VC05/025911
Policy No. Z/21/VC05/008566-001
Accident Date 08/06/2022
Inspection Date 13/06/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22005557/Epa3q2 Date: 03/08/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM (FOR MANDATE ONLY)				
	Insured Veh.	YN 8473X	Veh. Inspected	XD 8967C
	Policy No.	Z/21/VC05/008566-001	Coverage (\$)	0.00
	Claim No.	21/22/22/VC05/025911	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	10/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	UD TRUCKS GKB5ELDHNT	c.c	10837
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	GKB5E00240	Colour	YELLOW
	Odometer	666102 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	DUNLOP	4 mm
	L/H Front Tyre	295/80 R22.5	DUNLOP	4 mm
	R/H Rear Tyre	295/80 R22.5	DUNLOP	4 mm
	L/H Rear Tyre	295/80 R22.5	DUNLOP	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/06/2022	Inspection Date	13/06/2022
	Survey held at	SIN SHENG AUTO WORKSHOP PTE LTD 5 TUAS AVENUE 3, SINGAPORE 639405		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 8967C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT PANEL	DENTED	2,980.50	2,980.50
1	FRONT GRILLE	BROKEN	895.50	895.50
1	GRILLE LOWER	NOT NECESSARY	865.50	-
1	'UD' LOGO	NECESSARY	325.50	325.50
1	'QUON' LOGO	NECESSARY	165.50	165.50
1	MIRROR STAY ,LH	BENT	958.50	958.50
1	MIRROR STAY BRACKET LOWER	BROKEN	287.50	287.50
1	MIRROR STAY BRACKET WITH MOTOR ,UPPER	JAMMED	1,785.50	1,785.50
1	ROUND MIRROR	BROKEN	265.50	265.50
1	SIDE MIRROR	NOT NECESSARY	325.50	-
1	UNDER VIEW MIRROR	BROKEN	275.50	275.50
	TO REDO LOGO .		280.00	200.00
	LESS 30% DISCOUNT		-2,739.15	-2,381.85
			6,671.35	5,757.65
	<u>LABOUR</u>			
	TO PANEL BEAT/ REPAIR FRONT BODY TO DISMANTLE /REPLACE ABOVE -MENTIONED PARTS.		850.00	500.00
	TO SPRAY PAINTING ON AFFECTED AREAS .		850.00	450.00
			1,700.00	950.00
GRAND TOTAL			8,371.35	6,707.65
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,350.00

Report Ref No. CC4/LPC22005557/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XD 8967C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XD 8967C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XD 8967C

RE-INSPECTION

