



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

Vehicle No : 643472L
 Make/Model : Y124KA
 CHASSIS NO : _____

INDEPENDENT SURVEYOR	
DIRECT SETTLEMENT	☒

WORK SHOP REPAIRER ESTIMATE

Date: 13.6.22

Estimate cost of repair to the above mentioned

MARKING UNIT \$ AMOUNT (\$\$) REMARKS

NO.	QTY	List Items	MARKING	UNIT \$	AMOUNT (\$\$)	REMARKS
1	1	LH FRONT DOOR Dented ✓		\$ -	\$ 1461.35	
2	1	LH FRONT DOOR TOP MOLDING ^{up} new x. ✓		\$ -	\$ 74.10	
3	1	LH FRONT DOOR OUTER HANDLE Lt ✓		\$ -	\$ 210.10	
4	2	LH FRONT DOOR HINGE TOP/BOTTOM But ✓		\$ 73.20	\$ 146.40	
5	1	LH FRONT DOOR LOCK Dented ✓		\$ -	\$ 509.40	
6	1	LH FRONT DOOR WEATHER STRIP new x ✓		\$ -	\$ 326.40	
7	1	LH FRONT DOOR INNER TRIM BOARD Build ✓		\$ -	\$ 606.20	
8	1	LH FRONT DOOR INNER BOARD CLIP ^{new} new ✓		\$ -	\$ 55.00	
9	1	LH FRONT CORNER PANEL Dented ✓		\$ -	\$ 258.10	
10	1	LH FRONT LOWER STEP PANEL Lt ✓		\$ -	\$ 110.33	
11	1	LH FRONT SIDE MIRROR RACK new x ✓		\$ -	\$ 259.10	
12	1	LH FRONT SIDE MIRROR RACK MARKING x. ✓		\$ -	\$ 157.20	
13	1	LH FRONT HEAD LAMP Build ✓		\$ -	\$ 690.40	
14	1	FRONT BUMPER Dented ✓		\$ -	\$ 461.30	
15	1	LH FRONT METAL RIM Lt ✓		\$ -	\$ 400.15	
16	1	LH FRONT SHOCK ABSORBER But ✓		\$ -	\$ 110.20	
17	1	LH FRONT WHEEL BEARING Build ✓		\$ -	\$ 201.30	
18	2	LH FRONT WHEEL BEARING OIL SEAL. Build ✓		\$ 65.10	\$ 130.20	
19	1	LH FRONT WHEEL STARING HUB Build ✓		\$ -	\$ 210.10	
20	1	LH REAR CORNER PANEL. Regr x. ✓		\$ -	\$ 1745.10	

REMARKS:

NO OF DAYS:	
AGREED FIGURE/LUMP SUM:	\$ -
SURVEYOR NAME	CONTACT:
EMAIL ADD:	



TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

Vehicle No : 4434726
Make/Model : 7/84 MA.
CHASSIS NO :
Estimate : f

INDEPENDENT SURVEYOR	
DIRECT SETTLEMENT	☒

WORK SHOP REPAIRER ESTIMATE

Date: 13.6.22

Estimate cost of repair to the above mentioned

MARKING	UNIT \$	<u>AMOUNT (\$\$)</u>	REMARK:
---------	---------	----------------------	---------

NO.	QTY	List Items	UNIT	PRICE	AMOUNT	REMARKS
1	1	RH FRONT METAL RIM	ct	✓	\$ -	\$ 400.15
2	1	RH FRONT WHEEL BEARING	Pair	✓	\$ -	\$ 201.30
3	1	RH FRONT WHEEL BEARING HUB	Pair	✓	\$ -	\$ 210.10
4	1	RH FRONT SHOCK ABSORBER	Best	✓	\$ -	\$ 110.20
5	1	RH FRONT STEERING BOX RACK LINK	Best	✓	\$ -	\$ 240.30
6	2	RH REAR METAL RIM INNER/OUTER	Best	✓	\$ 310.30	\$ 620.60
7	1	RH REAR WHEEL BEARING	Pair	✓	\$ -	\$ 201.30
8	1	RH REAR WHEEL EXTER SHAFT	Pair	✓	\$ -	\$ 606.10
9	1	REAR EXTER GEAR BOX	Pair	✓	\$ -	\$ 4030.35
10	2	RH REAR WHEEL OIL SEAL	Pair	✓	\$ 65.10	\$ 130.20
11	1	LH SIDE SHAFT	Pair		\$ -	\$ -
12	1	FRONT CROSS MEMBER	Best	✓	\$ -	\$ 1654.89
13		Rear Axle Carrier	Best	✓	\$ -	\$ 4010.35
14		Rear Brake Drum	400 mm	X	\$ -	\$ 201.10
15					\$ -	\$ -
16					\$ -	\$ -
17					\$ -	\$ -
18					\$ -	\$ -
19					\$ -	\$ -
20					\$ -	\$ -

REMARKS:

REMARKS:

NO OF DAYS:	
AGREED FIGURE/LUMP SUM:	\$ -
SURVEYOR NAME	CONTACT:
EMAIL ADD:	



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

Vehicle No :

8443A72L

Make/Model :

Y/DYNA.

CHASSIS NO :

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

WORK SHOP REPAIRER ESTIMATE

Date:

Estimate cost of repair to the above mentioned

MARKING UNIT \$ AMOUNT (\$\$) REMARKS

NO.	QTY	List Items	MARKING	UNIT \$	AMOUNT (\$\$)	REMARKS
1		PANEL BEAT		\$ -	\$ 2000. 800	
2				\$ -	\$ -	
3		SPRAY PAINT		\$ -	\$ 1800. 1000	
4				\$ -	\$ -	
5		TO REMOVE/REPAIR L.H FRONT UNDERCARRIAGE		\$ -	\$ 250. 220	
6				\$ -	\$ -	
7		TO REMOVE/REPAIR FRONT WHEEL HUB		\$ -	\$ 350. 280	
8				\$ -	\$ -	
9		TO REMOVE/REPAIR REAR WHEEL HUB		\$ -	\$ 450. 350	
10		STEER BOX.		\$ -	\$ -	
11				\$ -	\$ -	
12		GEAR BOX OIL.		\$ -	\$ 120. 80	
13				\$ -	\$ -	
14		WHEEL ALIGNMENT.		\$ -	\$ 80.	✓
15				\$ -	\$ -	
16		RUST PROOF		\$ -	\$ 150. 109	
17				\$ -	\$ -	
18				\$ -	\$ -	
19				\$ -	\$ -	
20				\$ -	\$ -	

REMARKS:

NO OF DAYS:	08 Days.
AGREED FIGURE/LUMP SUM:	\$ -
SURVEYOR NAME	CONTACT:
EMAIL ADD:	