



## TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

Our Ref : GBG9296T

Your Ref : S2M040C3

### AXA INSURANCE SINGAPORE PTE LTD

27 June 2022

8 SHENTON WAY  
#24-01 AXA TOWER  
SINGAPORE 068811

Attn: MOTOR CLAIMS DEPT

Dear Sir / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: GBG9296T & SHC8871P ON 30/04/2022 @ 13:45 HRS ALONG  
BEDOK NORTH ROAD

---

The vehicle had been surveyed by your appointed surveyor and repaired to our client's satisfaction.

We hereby submit the details of claim as follow:

Cost Of Repair	:	S\$4,440.50
Loss Of Use (\$ 120.00 x 5 days)	:	S\$600.00
Additional Loss Of Use (\$ 120.00 x 1 days) - Weekend	:	S\$120.00
GIA / LTA Search	:	S\$7.45
		<u>S\$5,167.95</u>


Kindly revert within SEVEN days. Failing which we reverse our rights to refer the matter to our solicitors.

Your kind attention to the matter would be much appreciated.

Yours faithfully,

---

TONG LUCK AUTO PTE LTD



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

## TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)  
1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531

TEL : 6849 8118

FAX :

YOUR REF NO : S2M040C3

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 30/04/2022

TP VEHICLE NO : SHC8871P

NO : AR202206-0066  
CLAIM NO : QUOT202206-000022(01)  
DATE : 27/06/2022  
POLICY NO : 999995580  
VEH REG : GBG9296T  
MAKE/MODEL : NISSAN NV350 PANEL VAN  
2.5 5AT 5DR EURO V  
CHASIS NO : JN1MC2E26Z0009700  
ENGINE NO : YD25002832B  
REG. DATE : 2017

## Final Repair Cost to Vehicle No : GBG9296T

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
<b>NET PRICE</b>			
1 Tailgate	1	2,597.90	2,597.90
2 Tailgate centre logo	1	79.90	79.90
3 Tailgate 'NV350' emblem	1	85.25	85.25
4 Tailgate 'URVAN' emblem	1	85.25	85.25
5 Rear bumper	1	667.20	667.20
6 Rear bumper retainer - LH	1	181.00	181.00
			<u>3,696.50</u>
		Less 10%	<u>369.64</u>
			3,326.86
<b>SPECIAL NET</b>			
7 Rear windscreen sealant	1	40.00	40.00
8 Tailgate "70km/h" sticker	1	12.00	12.00
9 Tailgate '5 pax' sticker	1	12.00	12.00
10 Rear bumper clips (set)	1	50.00	50.00
			<u>114.00</u>
<b>LABOUR</b>			
12 To remove and refit rear windscreen glass	1	120.00	120.00
13 To transfer damaged tailgate interior mechanism to new tailgate	1	60.00	60.00
14 To remove and refit rear bumper sensor	1	50.00	50.00
15 To check and rectify wiring system	1	15.00	15.00
16 To panel beat and straighten rear floorboard panel, LH rear rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	400.00	400.00
17 To putty and spray paint on affected areas	1	400.00	400.00
18 To supply art works & paste decal on LH side panel and tailgate	1	750.00	750.00
			<u>1,795.00</u>



## TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

### TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531

TEL : 6849 8118

FAX :

YOUR REF NO : S2M040C3

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 30/04/2022

TP VEHICLE NO : SHC8871P

NO : AR202206-0066

CLAIM NO : QUOT202206-000022(01)

DATE : 27/06/2022

POLICY NO : 999995580

VEH REG : GBG9296T

MAKE/MODEL : NISSAN NV350 PANEL VAN  
2.5 5AT 5DR EURO V

CHASIS NO : JN1MC2E26Z0009700

ENGINE NO : YD25002832B

REG. DATE : 2017

### Final Repair Cost to Vehicle No : GBG9296T

Description	Quantity	Unit Price	Amount
		<del>S\$</del>	<del>S\$</del>
		AMOUNT :	S\$ 5,235.86
		LUMP SUM DISCOUNT :	S\$ -1,085.86
		TOTAL :	S\$ 4,150.00
		ADD GST @ 7% :	S\$ 290.50
		GRAND TOTAL :	<u><u>S\$4,440.50</u></u>

SINGAPORE DOLLARS FOUR THOUSAND FOUR HUNDRED AND FORTY AND CENTS FIFTY ONLY

TONG LUCK AUTO PTE LTD

E. & O.E.

AUTHORISED SIGNATURE

## AUTHORISATION LETTER

I, DAIMLER FLEET MANAGEMENT S'PORE PTE LTD of 1 GATEWAY DRIVE #15-08 WESTGATE TOWER SINGAPORE 608531, owner of GBG9296T hereby authorize TONG LUCK AUTO PTE LTD to act for me with my respect to our claim for repair costs and/or rental and/or loss of use for our vehicle no.: GBG9296T that was damaged pursuant to the accident which occurred on 30/04/2022 ALONG BEDOK NORTH ROAD involving vehicle nos: SHC8871P

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the

Dated this 8th day of June 2022

  
Signed by third party claimant



  
TONG LUCK AUTO PTE LTD



> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 08 Jun 2022 / 13:58:21

Receipt Date/Time : 08 Jun 2022 / 13:58:21

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-220608-002100

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - SHC8871P				
As at 30 Apr 2022/13:45:00				
Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SHC8871P Enquiry Fee 20220608135652542862	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
518834XXXXXX2002		eNETS Credit Card		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## Enquire Vehicle's Insurance Particulars

### Thank You!

The insurance details of the vehicle you enquired can be found below. If you have entered a valid email address, a copy would have been sent to you.

**Vehicle No.**  
SHC8871P

**Incident Date/Time**  
30 Apr 2022 / 13:45:00

**Insurance Company Name**  
AXA INSURANCE PTE LTD

[Save as PDF](#)

[OK →](#)

[Print](#)