



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SHC8871P

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 30/04/2022

TP VEH REG NO : SHC8871P

ESTIMATE

NO : QUOT202206-000022(00)

DATE : 08/06/2022

POLICY NO : 999995580

VEH REG NO : GBG9296T

MAKE/MODEL : NISSAN NV350 PANEL VAN 2.5
5AT 5DR EURO V

CHASSIS NO : JN1MC2E26Z0009700

ENGINE NO : YD25002832B

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG9296T

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Tailgate <i>2597.90</i>	1	2,597.90	2,597.90 ✓
2 Tailgate weatherstrip	1	167.00	167.00 X
3 Tailgate trimboard clips	15	5.50	82.50 X
4 Tailgate centre logo	1	79.90	79.90 —
5 Tailgate 'NV350' emblem	1	85.25	85.25 —
6 Tailgate 'URVAN' emblem	1	85.25	85.25 —
7 Rear end panel (outer)	1	216.00	216.00 X
8 Rear bumper <i>667.20</i>	1	667.20	667.20 —
9 Rear bumper reinforcement	1	667.20	667.20 X
10 Rear bumper retainer - LH	1	181.00	181.00 —
11 Rear bumper clips	15	5.50	82.50 <i>30.00</i>
12 Taillamp assy - LH		247.30	247.30 X
			5,159.00
		Less 10%	515.89
			4,643.11
SPECIAL NET			
13 Rear windscreen sealant	1	60.00	60.00 <i>40.00</i>
14 Tailgate "70km/h" sticker	1	25.00	25.00 <i>12.50</i>
15 Tailgate '5 pax' sticker	1	25.00	25.00 <i>12.50</i>
			110.00
LABOUR			
16 To remove and refit rear windscreen glass	1	150.00	150.00 <i>120.00</i>
17 To transfer damaged tailgate interior mechanism to new tailgate	1	120.00	120.00 <i>60.00</i>
18 To remove and refit rear bumper sensor	1	100.00	100.00 <i>50.00</i>
19 To check and rectify wiring system	1	80.00	80.00 <i>15.00</i>
20 To panel beat and straighten rear floorboard panel, LH rear rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 <i>400.00</i>
21 To putty and spray paint on affected areas	1	1,000.00	1,000.00 <i>400.00</i>
22 To supply art works & paste decal on LH side panel and tailgate	1	1,800.00	1,800.00 <i>750.00</i>
			4,250.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SHC8871P

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 30/04/2022

TP VEH REG NO : SHC8871P

ESTIMATE

NO : QUOT202206-000022(00)

DATE : 08/06/2022

POLICY NO : 999995580

VEH REG NO : **GBG9296T**

MAKE/MODEL : NISSAN NV350 PANEL VAN 2.5
5AT 5DR EURO V

CHASSIS NO : JN1MC2E26Z0009700

ENGINE NO : YD25002832B

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG9296T

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 9,003.11
		ADD GST @ 7%	630.22
		GRAND TOTAL	S\$ 9,633.33

SINGAPORE DOLLAR NINE THOUSAND SIX HUNDRED THIRTY-THREE AND CENTS THIRTY-THREE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE