

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	ICE SINGAPORE PL	Ref:	CS/SMO22005565/Aqy3e2	
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623	Date:	16/08/2022	
			Code	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 7706X	Veh. Inspected	SMD 9661H	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD2202035/THE(nr)	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	13/06/2022	
2.	Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	MR2B23F3901143036	Colour	SILVER	
	Odometer	159978 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
	L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
	R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
	L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	11/06/2022	Inspection Date	13/06/2022	
	Survey held at	J.E.W AUTO PTE LTD	•		
		60 JALAN LAM HUAT #03-72 CARROS CENTRE SINGAPORE 737869			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
		OF TO VOLID INICTOLICATIONS AN	E HAVE NOT AUTHORIC	ED DEDAIDE	
5h				ED REPAIRS.	
5b.	B)IN ACCORDANG		Days of Repair	rking Days	