



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO22005565/y3 Date: 13/06/2022 Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	YP 7706X	Veh. Inspected	SMD 9661 H
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	MR JOHN	Assign Date	13/06/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
	Accident Date	11/06/2022	Inspection Date	
	Survey held at	J.E.W AUTO PTE LTD 60 JALAN LAM HUAT #03-72 CARROS CENTRE SINGAPORE 737869		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			