



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2206530

INV Date 19/10/2022

Reference CC4/LPC22005566/Epa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SDJ 3618Z
Insured Veh. GR 9999G
Claim No. 22/22/22/VC05/025887
Policy No. Z22VC05009694
Accident Date 02/06/2022
Inspection Date 20/06/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22005566/Epa3q2 Date: 19/10/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GR 9999G	Veh. Inspected	SDJ 3618Z	
Policy No.	Z22VC05009694	Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/025887	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	08/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMGK5850GX201858	Colour	RED	
Odometer	63272 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/50 R16	YOKOHAMA	4 mm	
L/H Front Tyre	185/50 R16	YOKOHAMA	4 mm	
R/H Rear Tyre	185/50 R16	YOKOHAMA	4 mm	
L/H Rear Tyre	185/50 R16	YOKOHAMA	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/06/2022	Inspection Date	20/06/2022	
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDJ 3618Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	50.00	50.00
1	PANEL COMP ,L.FR DOOR (SN)	TO REPAIR SEE LABOUR	617.70	-
1	TAPE SETL.FR.DOOR (SN)	NOT NECESSARY	26.85	-
1	PANEL COMP,L.RR.DOOR (SN)	DENTED	573.90	573.90
1	TAPEL.RR.DOOR SASH (SN)	NECESSARY	11.55	11.55
1	SUB SEALL.RR.DOOR (SN)	NOT NECESSARY	5.55	-
1	SUB SEALL.RR.DOOR CENTER (SN)	NOT NECESSARY	35.10	-
1	SEALRR.DOOR LOWER (SN)	NOT NECESSARY	2.85	-
1	PANEL SET ,L.SIDE SILL (SN)	DENTED	189.52	189.52
1	PANEL SET ,L.RR. OUTSIDE (SN)	DENTED	456.30	456.30
1	GARNISH ASSY,L.SIDE SILL (SN)	BROKEN	311.62	311.62
1	DISKALUMINIUM WHEEL 16X6J (SN)	NOT NECESSARY	269.02	-
1	FACERR.BUMPER (SN)	BROKEN	401.92	401.92
1	GARNISHL.RR.BUMPER (SN)	NOT NECESSARY	11.40	-
1	SPACERR.RR.BUMPER (SN)	BROKEN	8.62	8.62
1	SPACERL.RR.BUMPER (SN)	BROKEN	8.62	8.62
1	CLIP,BUMPER (SN)	NECESSARY	1.72	1.72
			2,982.24	2,013.77
	<u>LABOUR</u>			
	RESET VEHICLE SMART ENTRY SYSTEM.		560.00	450.00
	REMOVE & REINSTALL REVERSE SENSORS.		280.00	180.00
	INSPECT RR LIGHTING MECHANISMS PERFORM WATER.		280.00	180.00
	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST.	NOT NECESSARY	560.00	-
	REMOVE & TRANSFER ITEMS TO NEW RR L DR ADJUST.		560.00	560.00
	BODY UNDERSIDE COATING .		380.00	280.00
	BODY JOINT SEALANT FR DR .	NOT NECESSARY	120.00	-
	BODY JOINT SEALANT RR DR .		120.00	120.00
	REMOVE & INSTALL ROOF LINING GARNISHES SEATS.	NOT NECESSARY	650.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	STRAIGHTEN ALIGN RR L FENDER & RENEW DAMAGE PARTS.INCLUSIVE OF THE REPAIR OF PANEL COMP ,L.FR DOOR .		3,900.00	3,900.00
	SPRAY PAINTING ON REPIARED OR REPLACED AREAS .		3,120.00	3,120.00
	WHEEL ALIGNMENT.		180.00	180.00
			10,710.00	8,970.00
GRAND TOTAL			13,692.24	10,983.77

RECOMMENDED COST OF REPAIRS				10,983.77
------------------------------------	--	--	--	------------------

Report Ref No. CC4/LPC22005566/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDJ 3618Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDJ 3618Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

