

HONDA

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Page 1

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SDJ3618Z
Chassis No : JHMGK5850GX201858
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : CHONG SHIH-YA
Ins Policy No. :
Date of Accident : 2/6/2022

Document No. : SQT22001609
Date : 6. Jun 2022
Customer No. : WZL009
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B31020707
Date | Time : 6. Jun 2022 9:46:53 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHONG SHIH-YA OWNER INSURER: LIBERTY ACC DATE: 02/06/2022 SURVEYED BY: DATE: REF NO: TP INSURER: LOMPAC TP VEH: GR9999G						
67050-T5A-N10ZZ	PANEL COMP,L.FR.DOOR <i>x R</i>	1	823.60	25	617.70	43.24	660.94
67364-T5A-003	TAPE SETL.FR.DOOR <i>x nn</i>	1	35.80	25	26.85	1.88	28.73
67550-T5A-N10ZZ	PANEL COMP,L.RR.DOOR <i>nn</i>	1	765.20	25	573.90	40.17	614.07
67865-T5A-003	TAPEL.RR.DOOR SASH <i>7 nn</i>	1	15.40	25	11.55	0.81	12.36
72864-T5A-J01	SUB SEALL.RR.DOOR <i>7 x nn</i>	1	7.40	25	5.55	0.39	5.94
72865-T5A-013	SUB SEALL.RR.DOOR CENTER <i>7 x nn</i>	1	46.80	25	35.10	2.46	37.56
72826-T5A-003	SEALRR.DOOR LOWER <i>7 x nn</i>	1	3.80	25	2.85	0.20	3.05
04641-TAS-320ZZ	PANEL SET,L.SIDE SILL <i>nn</i>	1	252.70	25	189.52	13.27	202.79
04646-TAS-330ZZ	PANEL SET,L.RR.OUTSIDE <i>(per fl) nn</i>	1	608.40	25	456.30	31.94	488.24
71850-T5B-003ZB	GARNISH ASSY,L.SIDE SILL <i>BR</i>	1	415.50	25	311.62	21.81	333.43
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J <i>x Pllch NN</i>	1	358.70	25	269.02	18.83	287.85
04715-T5B-000ZZ	FACERR.BUMPER <i>BR</i>	1	535.90	25	401.92	28.13	430.05
71507-T5A-000	GARNISHL.RR.BUMPER <i>7 x nn</i>	1	15.20	25	11.40	0.80	12.20
71593-T5A-000	SPACERR.RR.BUMPER <i>BR</i>	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER <i>BR</i>	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER <i>nc</i>	1	2.30	25	1.72	0.12	1.84
Sum Item					2932.24	205.25	3,137.49
BOSUN	SUNDRIES <i>/ nec</i>	1	50.00		50.00	3.50	53.50

Printed on 6/6/2022 10:09:37 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Page 2

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SDJ3618Z
Chassis No : JHMGK5850GX201858
Model : JAZZ 1.5VTIR CVT 16YM
Owner's Name : CHONG SHIH-YA
Ins Policy No. :
Date of Accident : 2/6/2022

Document No. : SQT22001609
Date : 6, Jun 2022
Customer No. : WZL009
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B31020707
Date | Time : 6, Jun 2022 9:46:53 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00	450 /	560.00	39.20	599.20
BA02R	REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)	1	280.00	180 /	280.00	19.60	299.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00	180 /	280.00	19.60	299.60
BKDR11R	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	1	560.00	X	560.00	39.20	599.20
BKDR21R	REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST	1	560.00	/	560.00	39.20	599.20
BOBC	BODY UNDERSIDE COATING (N)	1	380.00	280 /	380.00	26.60	406.60
BOJSE	BODY JOINT SEALANT FR DR	1	120.00	X	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT RR DR	1	120.00	/	120.00	8.40	128.40
BMI01D	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	1	650.00	X (photo)	650.00	45.50	695.50
BKRP21S	STRAIGHTEN ALIGN RR L FENDER & RENEW DAMAGE PARTS 6 x 650	1	3900.00	/	3900.00	273.00	4173.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P) 520 x 5	1	3120.00	/	3120.00	218.40	3338.40
Sum Labor					10580.00	740.60	11,320.60
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	/	180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

Survey By

Steve (LKR)

Date & Time

20/6/22, 11.30

Excess

12 IL

Status

12 H L

Signature

P/P
M P/L L

Total Amount 13,692.24 958.45 14,650.69

Total (Inclusive of GST) 14,650.69

Printed on 6/6/2022 10:09:37 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

- Insurance notify of the following:
- To be resurveyed after spray painting
 - To be resurveyed damaged part(s) during resurvey
 - This survey is subject to confirmation
 - This survey is on a "Without Prejudice" basis
 - No legal condition(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: