



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0112798 / LONPAC
Chassis No: JHMGK5850GX201858
License No: SDJ3618Z
Mileage: 63272
Engine No: L15B31020707

Document No: SVO22028058
Printed By: IVANTEO
Order Date: 20. June 2022
Order Time: 11:10:45 AM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHONG SHIH-YA OWNER INSURER: LIBERTY ACC DATE: 02/06/2022 SURVEYED BY: DATE: REF NO: TP INSURER: LOMPAC TP VEH: GR9999G						
67550-T5A-N10ZZ	PANEL COMP,L.RR.DOOR	1	765.20	25	573.90	40.17	614.07
67865-T5A-003	TAPEL.RR.DOOR SASH	1	15.40	25	11.55	0.81	12.36
04641-TAS-320ZZ	PANEL SET,L.SIDE SILL	1	252.70	25	189.52	13.27	202.79
04646-TAS-330ZZ	PANEL SET,L.RR.OUTSIDE	1	608.40	25	456.30	31.94	488.24
71850-T5B-003ZB	GARNISH ASSY,L.SIDE SILL	1	415.50	25	311.62	21.81	333.43
04715-T5B-000ZZ	FACERR.BUMPER	1	535.90	25	401.92	28.13	430.05
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	1	2.30	25	1.72	0.12	1.84
	SUM PARTS:				1,963.77	137.45	2,101.22
BOSUN		1	50.00		50.00	3.50	53.50
	SUNDRIES						
BC012R		1	450.00		450.00	31.50	481.50
	RESET VEHICLE SMART ENTRY SYSTEM						
BA02R		1	180.00		180.00	12.60	192.60
	REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)						
BML02I		1	180.00		180.00	12.60	192.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BKDR21R		1	560.00		560.00	39.20	599.20
	REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS.(N)						
BOBC		1	280.00		280.00	19.60	299.60
	BODY UNDERSIDE COATING (N)						
BOJSE		1	120.00		120.00	8.40	128.40
	BODY JOINT SEALANT RR DR						
BKRP21S	0669	1	3,900.00		3,900.00	273.00	4,173.00
	STRAIGHTEN ALIGN RR L FENDER & RENEW DAMAGE PARTS						
	DAMAGE PARTS.						
BP05R	1847	1	3,120.00		3,120.00	218.40	3,338.40
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)						
	SUM LABOUR:				8,840.00	618.80	9,458.80
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
	SUM EXT SERVICE:				180.00	12.60	192.60
	TOTAL SGD				10,983.77	768.85	11,752.62

Total Payable (SGD)

11,752.62



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0112798 / LONPAC
Chassis No: JHMGK5850GX201858
License No: SDJ3618Z
Mileage: 63272
Engine No: L15B31020707

Document No: SVO22028058
Printed By: IVANTEO
Order Date: 20. June 2022
Order Time: 11:10:45 AM
Service Advisor: IVAN TEO BOON KIAT

GST Amount is calculated from individual line(s)