

Vehicle Damage Assessment Report for [SJL8583A]

Estimate Created: 13/06/2022 06:21 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 07/10/2022 04:12 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	Claim Number
Claim Type	TP
Workshop	LKK_Auto_Consultants_Pte_Ltd
	Reference Number

Vehicle Information

Brand	Toyota	Model	Vios
Engine Type			
License Plate Number	SJL8583A	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review based on information provided by Cty Auto PTE LTD: Concluded lump sum repair cost of \$3450 with 7 working days. Insurlogic 4 (07/10/2022 04:11)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
RH FENDER		1	637.70	0.00 %	637.70
RH FRONT DOOR		1	1663.50	0.00 %	1,663.50
RH REAR DOOR		1	905.20	0.00 %	905.20
RH SIDE MIRROR		1	1189.60	0.00 %	1,189.60
RH DOOR PROTECTOR		1	374.80	0.00 %	374.80

Parts Subtotal 4,770.80

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
TO KNOWCK JACKOUT DAMAGED PART, PANEL BEAT, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS	RnR	700.00	0.00 %	700.00
TO REMOVE AND INSTALL DOOR GLASS	RnR	120.00	0.00 %	120.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING	Full spray	1000.00	0.00 %	1,000.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 820.00

Paint Labor Subtotal 1,000.00

Labor Subtotal 1,820.00

Summary

Repair Cost	6,590.80
Discount(48 %)	(3,140.80)
	3,450.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	3,450.00