

(08/11/13) wef  
ASS. REC. BY: Marcus

REF: CS/AG/22005568/4943

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SJL 54154  
at Workshop m/s 2.0ml  
of \_\_\_\_\_  
Insured: SMP 4846L  
Policy No. \_\_\_\_\_  
Claims No. C10015739/JT  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_



(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.  
Bal. or Market Value: \$12k  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 5 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS 6396  
Date: \_\_\_\_\_ Person Contacted: Ben  
Vehicle: IN / OUT

Veh No: SJL 54154 Yr Regn: 01/12/08  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA  
Make: Toyota wish c.c. 1794  
Colour: S-hm A/C: Insured / Std / NI / NA  
Sp. Reading: 173274 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: JTDER12W803000989  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 195/65-215  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 5 mm R/Bal. 5 mm  
L/Bal. 5 mm L/Bal. 5 mm  
D.O.A. 08/06/22 D.O.I. 14/6/22  
Survey held at \_\_\_\_\_  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Bolton Smith

see note 30-11-2023 LTAF 4675

Nett \$7325

30/6/22 L/s \$5000 informed Michael (Red B6703.49, 57%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1) 05/7/2022

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2)

Transportation:

Report Format : TP

Lump Sum / I.B.T. (\$) 5000

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL



# Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE & PERFORMANCE GST Registration No. 201118055N Company Registration No. 201118055N

Not Authorised  
1/5000  
Schys.  
Take photo of car  
14/6/22

## ESTIMATE

Lee Jia Sheng  
BLK 120B EDGEDALE PLAINS #11-295 Singapore  
822120

Contact : 96887403

Code : C102042  
Date in : 14/06/2022  
Vehicle Num. : SJL5415Y  
Model : TOYOTA WISH 1.8 AUTO  
Chassis/Eng# : JTDER12W803000989/1ZZ3160552

### Parts and Labour Assessment

| Description of part                                 | Qty             | Unit Price | Amount            |
|-----------------------------------------------------|-----------------|------------|-------------------|
| Rear bumper <i>Dis</i>                              | 1               | 501.80     | 501.80 <i>—</i>   |
| Rear bumper impact brackets L/R <i>N/S AD</i>       | 2               | 115.54     | 231.08 <i>12C</i> |
| Rear bumper reflector L/R <i>11</i>                 | 2               | 76.50      | 153.00 <i>X</i>   |
| Rear bumper side retainers L/R <i>3ent/1ent</i>     | 2               | 63.80      | 127.60 <i>—</i>   |
| Rear end panel <i>3od500</i>                        | 1               | 484.00     | 484.00 <i>—</i>   |
| Rear end panel inner top garnish <i>7W1</i>         | 1               | 255.20     | 255.20 <i>—</i>   |
| Rear tailgate <i>3od500</i>                         | 1               | 1329.90    | 1,329.90 <i>—</i> |
| Rear tailgate chrome garnish <i>Cne/3ent</i>        | 1               | 186.12     | 186.12 <i>—</i>   |
| Rear tailgate chrome garnish outer handle <i>11</i> | 1               | 177.21     | 177.21 <i>X</i>   |
| Rear tailgate dampers L/R <i>11</i>                 | 2               | 232.10     | 464.20 <i>X</i>   |
| Rear tailgate hinges L/R <i>11</i>                  | 2               | 63.58      | 127.16 <i>X</i>   |
| Rear tailgate inner trimboard <i>2e/cne</i>         | 1               | 332.20     | 332.20 <i>—</i>   |
| Rear tailgate inner trimboard handle <i>11</i>      | 1               | 332.20     | 332.20 <i>X</i>   |
| Rear tailgate lock <i>10/3W1</i>                    | 1               | 487.30     | 487.30 <i>—</i>   |
| Rear tailgate logo emblem <i>1ent</i>               | 1               | 52.80      | 52.80 <i>—</i>    |
| Rear tailgate stricker <i>NZ</i>                    | 1               | 60.50      | 60.50 <i>X</i>    |
| Rear tailgate weatherstrip <i>1W1</i>               | 1 <i>299.10</i> | 333.30     | 333.30 <i>—</i>   |



Tel: 62502115/66342112 Fax: 66342122

Email: [service@z-one.com.sg](mailto:service@z-one.com.sg) ; [enquiry@z-one.com.sg](mailto:enquiry@z-one.com.sg)

AUTOMOTIVE • PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

|                                                      |                  |   |        |                        |            |
|------------------------------------------------------|------------------|---|--------|------------------------|------------|
| Rear tailgate windscreen rubber moulding             | <i>neu</i>       | 1 | 132.00 | 132.00                 | ✓          |
| Rear tailgate wiper motor                            | <i>11</i>        | 1 | 560.01 | 560.01                 | X          |
| Rear taillamp inner panel L/R                        | <i>2</i>         | 2 | 358.71 | 717.42                 | X          |
| Rear taillamp L/R                                    | <i>0/5 neu</i>   | 2 | 507.10 | <i>455.10</i> 1,014.20 | <i>1/2</i> |
| Rear trunk panel                                     | <i>2</i>         | 1 | 568.81 | 568.81                 | X          |
| Rear trunk panel cardboard cover L/R                 | <i>11</i>        | 2 | 121.11 | 242.22                 | X          |
| Rear trunk panel cardboard cover support end garnish | <i>20m</i>       | 1 | 186.01 | 186.01                 | ✓          |
| Rear trunk panel upholstery mat                      | <i>11</i>        | 1 | 388.41 | 388.41                 | X          |
| Subtotal before discount                             |                  |   |        | 9,444.65               |            |
| Percentage discount 25%                              |                  |   |        | 2,361.16               |            |
| Sub-total 1                                          |                  |   |        | 7,083.49               |            |
| Rear bumper clips (set) (sn)                         | <i>1 set neu</i> | 1 | 30.00  | 30.00                  | ✓          |
| Rear <i>licence</i> bumper plate with holder (sn)    | <i>3 set</i>     | 1 | 50.00  | 50.00                  | <i>40</i>  |
| Rear end panel inner top garnish clips (set) (sn)    | <i>neu</i>       | 1 | 30.00  | 30.00                  | ✓          |
| Rear reverse sensor (set) (sn)                       | <i>1 set</i>     | 1 | 280.00 | 280.00                 | <i>200</i> |
| Rear spare tyre (sn)                                 | <i>11</i>        | 1 | 450.00 | 450.00                 | X          |
| Rear tailgate chrome garnish stay clips (set) (sn)   | <i>11</i>        | 1 | 50.00  | 50.00                  | X          |
| Rear windscreen sealant (sn)                         | <i>1m</i>        | 1 | 80.00  | 80.00                  | <i>40</i>  |
| Subtotal before discount                             |                  |   |        | 970.00                 |            |
| Percentage discount 0%                               |                  |   |        | 0.00                   |            |
| Sub-total 2                                          |                  |   |        | 970.00                 |            |
| Parts-total                                          |                  |   |        | 8,053.49               |            |



Tel: 62502115/66342112 Fax: 66342122

Email: [service@z-one.com.sg](mailto:service@z-one.com.sg); [enquiry@z-one.com.sg](mailto:enquiry@z-one.com.sg)

AUTOMOTIVE PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

## LABOUR

| Description                                                                                                                                                                     | Price            |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning.                                                                               | 120.00           |
| To remove, reinstall electrical wiring harness, check lighting. (to FR)                                                                                                         | 80.00            |
| To remove, refix / renew reverse sensor assy and rectify for proper functioning.                                                                                                | 100.00           |
| To remove, reinstall rear tailgate windscreen (to FR)                                                                                                                           | 180.00           |
| To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)                                                                           | 150.00           |
| To remove rear seat, dismantle                                                                                                                                                  | 120.00           |
| To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.                                                                             | 1,200.00         |
| To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. | 1,400.00         |
| Dismantle, repair and re-align rear wiper linkage and motor assy to proper functioning.                                                                                         | 150.00           |
| To apply anti-rust chemical on repaired and replaced panel.                                                                                                                     | 150.00           |
| <b>Labour Total</b>                                                                                                                                                             | <b>3,650.00</b>  |
| <b>Parts &amp; Labour Total</b>                                                                                                                                                 | <b>11,703.49</b> |

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-4944.67  
 252  
 3708.50  
 340  
 2220  
 6268.50  
 202  
 504