

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial PK 2 Singapore 569541
Tel : 64817221

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SMM 5243 K
Make/Model : Toyota Noah
Year : 2019

*Not Authorized
To Pay &
Remove After Paint
Today*

Fax : 64816131

| Qty | Description | Unit Price | Amount |
|-----|-------------|------------|--------|
|-----|-------------|------------|--------|

Estimate Cost Of Repair

| | | | |
|-------|----------------------------------|-----------|--|
| 1 pc | Rear tail-gate | <i>By</i> | \$1,750.80 <input checked="" type="checkbox"/> |
| 1 pc | Rear tail-gate glass moulding | <i>By</i> | \$185.70 <input checked="" type="checkbox"/> |
| 1 pc | Rear tail-gate emblem " Hybrid " | <i>By</i> | \$65.10 <input checked="" type="checkbox"/> |
| 1 pc | Rear tail-gate inner lock | <i>R</i> | \$285.60 <input checked="" type="checkbox"/> |
| 1 pc | Rear boot rubber | <i>R</i> | \$265.30 <input checked="" type="checkbox"/> |
| 1 pc | Rear bumper | <i>By</i> | \$1,255.90 <input checked="" type="checkbox"/> |
| 2 pcs | Rear bumper side retainer | <i>By</i> | \$155.70 <input checked="" type="checkbox"/> |
| | | | <u>\$311.40 X</u> |
| | | | \$4,119.80 |
| | | Less 25 % | \$1,029.95 |
| | | | <u>\$3,089.85</u> |

S Nett

| | | | |
|--------|------------------------------|------------------|--|
| 1 pc | Rear tail-gate glass sealant | <i>By</i> | \$40.00 <input checked="" type="checkbox"/> |
| 20 pcs | Rear bumper clip | <i>By</i> | \$2.00 <input checked="" type="checkbox"/> |
| 1 pc | Rear reverse sensor | <i>RI / Shen</i> | \$200.00 <input checked="" type="checkbox"/> |
| | | | <u>\$280.00</u> |

Labour charges

| | | |
|---|-------------------|-------------------------------------|
| Remove/renew the above parts including knocking, welding & cutting. | \$600.00 | <i>500</i> |
| To putty and spray paint | \$600.00 | <i>500</i> |
| Check and reconnect wiring | \$30.00 | <i>15</i> |
| To respray anti-rust proofing treatment | \$60.00 | <i>30</i> |
| Remove/refit rear windscreen to facilitate repair | \$120.00 | <input checked="" type="checkbox"/> |
| Remove/refit rear tail-gate mechanism to new door | \$100.00 | <i>60</i> |
| | <u>\$4,879.85</u> | |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey. Total
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: