

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF503P

Not Notified
 Repair B4 paint
 @ 4639-18

AAD2206-015

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHF503P

JTDKB3FU803093346

200303878K

TOYOTA

PRIUS GEN 4

04/06/2022

SGK1008G/ AIG.

15/01/2021

07 JUN 2022

- PART**
- 1 COVER, FRONT BUMPER
 - 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
 - 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
 - 1 ABSORBER, FRONT BUMPER ENERGY
 - 1 SUPPORT, FRONT BUMPER SIDE, RH
 - 1 COVER, FRONT BUMPER HOLE, RH
 - 1 MOULDING, FRONT BUMPER SIDE, RH
 - 1 UNIT ASSY, HEADLAMP, RH
 - 1 FENDER SUB-ASSY, FRONT RH
 - 1 LINER, FRONT FENDER, RH
 - 1 EMBLEM, SIDE PANEL, RH
 - 1 HOOD SUB-ASSY
 - 1 SUPPORT ASSY, HOOD
 - 1 HINGE ASSY, HOOD, LH
 - 1 HINGE ASSY, HOOD, RH
 - 1 COVER SUB-ASSY, FRONT PILLAR, UPR RH
 - 1 HUB CAP
 - 1 RIM

Washer Tank

219.10

Not

TOTAL \$ 4,271.80
25% \$ 1,067.95
\$ 3,203.85

Special Nett

- 1SET BUMPER CLIP FRT
- 1SET FRNT BUMPER RETAINER CLIP
- 1 FENDER LINER CLIP
- 1SET BONNET INSULATOR CLIP

\$ 95.00 *base*
 \$ 85.00 X
 \$ 65.00 X
 \$ 70.00 X

Trans-cab Auto Services Pte Ltd

AAD2206-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF503P

	TOTAL	\$	180.00	
	TOTAL PARTS	\$	3,383.85	
LABOUR				
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X	
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	4001	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X	
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	4 480.00	X	
To transfer of Fender fittings, attachments and perform water seepage test.	\$	4 480.00	X	
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X	
To check steering geometry and computer wheel alignment	\$	4 220.00	X	
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301	
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	4401	
To reinstall rear bumper parking sensor.	\$	4 170.00	X	
To Check Electrical Lighting Concerned.	\$	170.00	201	
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	4 380.00	X	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF503P

AAD2206-

To transfer of tire, rim and on wheel balancing.

\$ 220.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.

\$ 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ 380.00 X

TOTAL \$ 8,670.00

Over All Total \$ 12,053.85

(PART-BY-PART) Repair Days

25 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF503P

AAD2206-015

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SUPPLEMENTARY

SHF503P

JTDKB3FU803093346

200303878K

TOYOTA

PRIUS GEN 4

04/06/2022

SGK1008G/AIG

15/01/2021

PART

LIST

1 JAR ASSY, WINDSHIELD WASHER

\$ *Not* 219.10 ✓

TOTAL \$ 219.10

25% \$ 54.78

\$ 164.33

Vehicle Registration Number

SHF503P

Insurance Company

AXA Insurance Pte Ltd

Is the insured?

Yes

Name of Registered Owner

TRANS-CAB SERVICES PTE LTD

Company Reg No

200000878K

Email Address

claims@transcab.com.sg

Mobile Phone No

(Phone) +65-62878608

Alternative Phone No

(Office) +65-62876666

Vehicle Category

Private hire

Manufacturer

Toyota

Model

Prius

Variant

-

Exact purpose for which vehicle was being used at time of

Private hire

accident

Private hire

Are you claiming under your own insurance policy for repair to

No - Claiming third party

your vehicle?

No - Claiming third party

Vehicle Category

Taxi

Transmission

Auto

CC

1767

Insurance Company

AXA Insurance Pte Ltd

Name of Insurance Company

AXA Insurance Pte Ltd

Type of Coverage

ThirdParty

Fleet Policy

Yes

Policy Number

WEX/P2413997

Cover Note Number

-

Driver

-

Name of Driver

AB RAHMAN BIN EUSOPE

NRIC No

SXXXX967A