

A.S.S. REC-38V: TauREF: CS/CT1 22005578/T+43

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: 9920

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SML 6932DYr Regn: 2019, May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Shuttle Hybrid C.C. 1496Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 281727

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP7200 2113

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 185 / 60 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Five439

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 14/6/22Survey held at AP AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time | Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Rep. Format: _____

Lump Sum / L.B.H. ()

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL



AP AUTOMOTIVE SERVICES PTE LTD
 ROC / GST REG NO : 202022890H
 BLOCK 9006
 TAMPINES STREET 93 #01-202
 SINGAPORE 528840
 TEL: 6784 4465
 FAX: 6787 4886

ESTIMATION

DATE :
 VEHICLE : SML6932D
 MAKE / MODEL : HONDA SHUTTLE HYBRID

No.	Description	Unit	Unit Price	Amount
	PART REPLACEMENT			
	REAR TAILGATE	1	\$1,025.00	\$ 1,025.00
	REAR TAILGATE WINDSCREEN MOULDING	1	\$158.75	\$ 158.75
	REAR TAILGATE LOGO "HONDA"	1	\$98.75	\$ 98.75
	REAR TAILGATE LOGO "SHUTTLE"	1	\$84.88	\$ 84.88
	REAR TAILGATE LOGO "HYBRID"	1	\$106.38	\$ 106.38
	REAR TAILGATE WEATHERSTRIP	1	\$187.50	\$ 187.50
	REAR BUMPER	1	\$1,437.50	\$ 1,437.50
	REAR BUMPER REFLECTOR	2	\$88.75	\$ 177.50
	REAR BUMPER REFLECTOR GARNISH	2	\$140.50	\$ 281.00
	REAR BUMPER TOW HOOK COVER	1	\$107.50	\$ 107.50
	REAR BUMPER RETAINER	2	\$100.00	\$ 200.00
	REAR BUMPER BRACKET	2	\$131.25	\$ 262.50
	REAR BUMPER UNDER COVER	1	\$590.00	\$ 590.00
	END PANEL	1	\$615.83	\$ 615.83
	END PANEL TOP GARNISH	1	\$167.50	\$ 167.50
	REAR SMART LOCK ANTENNA	1	\$243.75	\$ 243.75
	REAR BUZZER	1	\$182.50	\$ 182.50
	Total			\$ 5,926.83
	Less 10%			\$ 592.68
	Sub Total			\$ 5,334.14

	S/NETT ITEMS			
	NUMBER PLATE	1	\$55.00	\$ 55.00
	REVERSE SENSOR	1	\$300.00	\$ 300.00
	TAILGATE WINDSCREEN SEALANT	1	\$120.00	\$ 120.00
	REAR TAILGATE INNER TRIM CLIPS	1	\$80.00	\$ 80.00
	REAR BUMPER CLIP (SET)	1	\$80.00	\$ 80.00
	END PANEL SEALANT	1	\$100.00	\$ 100.00
	END PANEL TOP GARNISH CLIP	1	\$80.00	\$ 80.00
	Total			\$ 815.00

LABOUR

	PANEL BEATING ON AFFECTED AREAS	1	\$1,400.00	\$ 1,400.00
	SPRAY PAINTING ON AFFECTED AREAS	1	\$1,200.00	\$ 1,200.00
	REMOVE AND REFIT REAR WINDSCREEN	1	\$200.00	\$ 200.00
	CHECK WIRINGS AND TAIL LAMP FUNCTIONS	1	\$100.00	\$ 100.00

WATER LEAK CHECK	1	\$100.00	\$	100.00	X
REMOVE AND REFIT UPHOLSTERY TO FACILITATE REPAIRS	1	\$200.00	\$	200.00	60
REMOVE AND REFIT REAR TAILGATE MECHANISM	1	\$200.00	\$	200.00	60
REMOVE AND REFIT REVERSE SENSOR AND CHECK FUNCTIONS	1	\$80.00	\$	80.00	30
APPLY ANTI RUST	1	\$120.00	\$	120.00	30
Part Replacement Amount			\$	6,149.14	
Total Amount For Labour			\$	3,600.00	
Total Amount			\$	9,749.14	

Taufik 97495749
 WP 14/6/22 @ 1130
 1/5 Resurvey after repair
 Taufik the 11hant.com
 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	674Z
Vehicle Details	
Vehicle No.:	SML6932D
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2022
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	LEB7102882
Chassis No.:	GP72002113
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$23,108.00
Original Registration Date:	30 May 2019
First Registration Date:	30 May 2019
Transfer Count:	0
Actual ARF Paid:	\$14,352.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2029
PARF Rebate Amount:	\$10,764.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,000.00
COE Rebate Amount:	\$33,058.00
Total Rebate Amount:	\$43,822.00

The information contained herein is correct as at 07 Jun 2022

OK