

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Not Authorized

11 Bay 8 25501

Resurvey After Paint

5 days

Make & Model : HONDA

CIVIC

Vehicle Number : SGY2340R

Quantity	Description	Repairer's Estimate
A - PARTS		
1	driver door (Rt)	Rt \$800 ✓
1	fender right rec	Rt \$1,200 X
1	fender right (middle)	Rt \$1,200 X
1	passenger door (Rear)	Rt \$800 ✓
1	fender right (back) Rt 537.50	Rt \$650 ✓
1	door locking system	Rt \$650 X
201		
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____		
B - SPECIAL NETT		
1	Front bumper clip set	nn \$60 X
1	Front fender shield RH clip set	nn \$60 X
LABOUR & MISC		
1	Checking of wiring, lghting & resetting	\$850 201
1	Remove and refit rear & front undercarriage	nn \$500 X
1	Wheel alignment	nn \$100 X
1	Remove and replace damaged parts	\$1,000
1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$2,000 } 6001
1	Respray including polishing and waxing on the changed body parts, repaired portortions where consistent to the accident	\$1,000 9001
Total Repair Cost :		\$10,870